Instruction Manual

PLEASE RETURN TO LIBRARIAN
ORG. 6-7744 M.S. 27-14
manual # 2

MODEL 883A

AC/DC
DIFFERENTIAL VOLTMETER

FLUKE
ELECTRONICS FOR INDUSTRY
INSTRUMENTS / COMPONENTS

JOHN FLUKE MFG. CO., INC.
P.O. Box 7428 Seattle, Washington 98133

March 15, 1966

PLEASE RETURN TO LIBRARIAN
ORG. 6-7744 M.S. 27-14
manual # 2

MODEL 883A

AC/DC
DIFFERENTIAL VOLTMETER

883A & 883AB serial no. 123 and above.

Copyright, John Fluke Mfg. Co., 1968

ERRATA

FLUKE MODELS 883AB AND 887AB

INTRODUCTION

Errors have been noted in the manuals for the Model 883AB and Model 887AB which should be corrected as explained in the following paragraphs.

MODELS 883AB AND 887AB

Battery installation illustrated in the Final Assembly photo in section V, page 5-6 (Model 883AB), and page 5-5 (Model 887AB) is in error in the designations of BT1 and BT3. Installation of replacement batteries according to those designations will result is serious damage to the Reference Voltage Supply as well as the batteries themselves. Change the reference designator BT1 to read BT3 and change the reference designator BT3 to read BT1.

MODEL 887AB

a. On page 5-4, delete R11. This part is correctly listed on page 5-8 as R545.

b. On page 5-5, change reference designator R11 to read R13.

c. On the schematic diagram, detail III, change R11 to read R545.

ERRATA

MODEL 883A AC/DC DIFFERENTIAL VOLTMETER

INTRODUCTION.

The following information should be considered as part of the instruction manual.

CHANGES.

1. Change the List of Replaceable Parts as follows:

PAGE 5-7

DELETE

*C2 and R13 provide meter damping. On some instruments, a different meter is used not requiring external damping. The above listing is the preferred replacement.

ADD

*C4 and *R15 provide meter damping. On some instruments, a different meter is used not requiring external damping. The above listing is the preferred replacement.

PAGE 5-8

DELETE							
Q101	Tstr, Si, NPN (use 4805-117135)	4805-153551	07910	CDQ10449	-		D
	Tstr, Si, NPN (use 4805-193870)	4805-117135	95303	2N2270	1	1	V
	Tstr, Si, NPN	4805-193870	04713	SS2104	8	3	U
ADD							
Q101	Tstr, Si, NPN	4805-203489	07910	CDQ10656	8	3	
DELETE							
Q102 to Q103	Tstr, Si, NPN (use 4805-193870)	4805-153551	07910	CDQ10449	8	3	T
	Tstr, Si, NPN	4805-193870	04713	SS2104	REF		U
ADD							
Q102 to Q103	Tstr, Si, NPN	4805-203489	07910	CDQ10656	REF		

PAGE 5-9

DELETE							
R131	Res, comp, 82Ω ±5%, 1/2W	4704-108746	01121	EB8205	1		
ADD							
R131	Res, comp, 2.7Ω ±10%, 1/2W	4704-108845	01121	EB27G1	1		

PAGE 5-11

DELETE							
G201	Chopper, electromechanical, SPDT, coated with epoxy resin	5901-162784 (881A-240)	89536	5901-162784	1	1	
ADD							
G201	Chopper, electromechanical, SPDT	5901-218255	80640	CH1403/84	1	1	

	DELETE					
Q202 to Q205	Tstr, Si, NPN (use 4805-193870)	4805-153551	07910	Same as Q102	REF	T
	Tstr, Si, NPN	4805-193870	04713	SS 2104		U
	ADD					
Q202 to Q205	Tstr, Si, NPN	4805-203489	07910	CDQ10656	REF	

PAGE 5-18

DELETE

1 These resistors are factory matched for each instrument. When ordering, include all information stamped on resistor.

ADD

1 Factory selected. If replacement is required, replace with new Resistor Set.

PAGE 5-22

	DELETE					
Q502 to Q5-6	Tstr, Si, NPN	4805-159855	07910	CDQ23102	1	1
	ADD					
Q502	Tstr, Si, NPN	4805-218081	04713	MPS6520	1	1
Q503 to Q506	Tstr, Si, NPN	4805-159855	07910	CDQ23102	1	1
	DELETE					
Q508	Tstr, Si, NPN (use 4805-193870)	4805-153551	07910	Same as Q102	REF	T
	Tstr, Si, NPN	4805-193870	04713	SS2104	REF	U
	ADD					
Q508	Tstr, Si, NPN	4805-203489	07910	CDQ10656	REF	

PAGE 5-23

	DELETE				
R510	Res, comp, 56K ±10%, 1/2W	4704-108472	01121	Same as R238	REF
	ADD				
R510	Res, comp, 33K ±10%, 1/2W	4704-178541	01121	EB3331	1

2. Change the Schematic Diagram as follows:

R131	DELETE	82
	ADD	2.7
R510	DELETE	56K
	ADD	33K

TABLE OF CONTENTS

SECTION	TITLE	PAGE
I	INTRODUCTION & SPECIFICATIONS	1-1
	1-1. Introduction	1-1
	1-5. Input Power	1-1
	1-7. Damage in Shipment	1-1
	1-9. Specifications	1-2
II	OPERATING INSTRUCTIONS	2-1
	2-1. Function of External Controls, Terminals and Indicators	2-1
	2-3. Preliminary Operation for Model 883A	2-1
	2-5. Preliminary Operation for Model 883AB.	2-3
	2-7. Zeroing Instructions	2-3
	2-9. Battery Charging	2-3
	2-10. Operation as a DC Differential Voltmeter	2-4
	2-11. Operation as an AC Differential Voltmeter	2-4
	2-12. Operation as a Conventional Voltmeter	2-4
	2-14. Measurement of Voltage Excursions about a Nominal Value	2-4
	2-15. Recording Voltage Excursions	2-5
	2-17. Use of 883A with an A88 Isolation Amplifier and a Recorder	2-5
	2-19. Use of 883A with a Recorder	2-5
	2-21. Measurement of High Resistance.	2-5
	2-24. Notes on Measuring AC or DC Voltages	2-6
	2-25. Ground Loop Precautions	2-6
	2-27. Use of Shorting Link	2-6
	2-29. Battery Checking	2-6
	2-31. Effect of Common Mode Voltages	2-6
	2-33. Notes on Measuring DC Voltages	2-6
	2-34. Effect of AC Components on DC Measurements	2-6
	2-36. Measurement of Negative Voltages	2-7
	2-38. Notes on Measuring AC Voltages	2-7
	2-39. Errors Due to Distortion	2-7
	2-41. Errors Due to Grounding	2-7
	2-43. Internal Converter Noise	2-7
	2-45. Most Sensitive Null Range on AC	2-8
III	THEORY OF OPERATION	3-1
	3-1. Introduction	3-1
	3-5. DC Input Attenuator	3-2
	3-7. DC Transistorized Voltmeter	3-2
	3-8. General	3-2
	3-10. Null Detector	3-2
	3-12. TVM Attenuator	3-2
	3-15. Input Resistance	3-3
	3-18. Chopper Drive Circuit	3-3
	3-20. Null Detector Power Supply	3-3
	3-22. Effect of AC Components on DC Measurements.	3-3
	3-24. TVM Gain and Zero Adjustments	3-3
	3-26. Recorder Output	3-4
	3-28. 0 to 11 Volt Reference	3-4
	3-29. General	3-4
	3-31. -18 Volt Power Supply	3-4
	3-33. Range Divider	3-4
	3-35. Kelvin-Varley Divider	3-4
	3-37. Adjustments.	3-4
	3-39. AC to DC Converter	3-5
	3-40. General	3-5
	3-42. Operation	3-5
	3-44. Adjustments	3-5
	3-46. AC-DC Polarity Switch	3-5
IV	MAINTENANCE	4-1
	4-1. Introduction	4-1
	4-3. Test Equipment	4-1
	4-5. Periodic Maintenance	4-1
	4-8. Performance Checking	4-1
	4-9. General	4-1
	4-11. Null Detector Check	4-4
	4-13. DC Differential Measurement Check	4-4
	4-15. AC Measurement Check	4-6
	4-17. Calibration	4-6
	4-18. General	4-6
	4-20. DC Differential Voltmeter Calibration	4-7
	4-27. AC to DC Converter Calibration	4-9
	4-38. Corrective Maintenance	4-10
	4-39. General	4-10
	4-41. Troubleshooting	4-10
	4-52. Electronic Adjustments	4-15
	4-61. Mechanical Drum Adjustments	4-17

SECTION	TITLE	PAGE
V	LIST OF REPLACEABLE PARTS	5-1
	5-1. Introduction	5-1
	5-4. How to Obtain Parts	5-1
	5-7. Abbreviations	5-2
	5-8. Prefix Symbols	5-2
	5-9. Quantity Symbols	5-2
	5-10. Special Notes and Symbols	5-2
	5-11. Use Code Effectivity	5-24
VI	ACCESSORIES	6-1
	6-1. Precision Voltage Dividers	6-1
	6-3. Isolation Amplifier	6-2
	APPENDIX A	
	WARRANTY	
	CIRCUIT DIAGRAM	

LIST OF ILLUSTRATIONS

FIGURE	TITLE	PAGE
Frontis-piece	Model 883A Differential AC/DC Voltmeter	v
2-1.	Location of Controls, Terminals, and Indicators	2-1
2-2.	Description of Controls, Terminals, and Indicators (Sheet 1 of 2)	2-2
2-2.	Description of Controls, Terminals, and Indicators (Sheet 2 of 2)	2-3
2-3.	VTVM Ranges	2-4
2-4.	Resistance Measurements	2-6
2-5.	Percent Error Due to Harmonic Distortion	2-7
2-6.	Signal Voltage With Converter Noise	2-8
3-1.	883A Differential Voltmeter Block Diagram	3-1
3-2.	Function of Polarity Switch	3-6
4-1.	Test Equipment Requirements (Sheet 1 of 2)	4-2
4-1.	Test Equipment Requirements (Sheet 2 of 2)	4-3
4-2.	Settings for Null Detector Check	4-4
4-3.	Differential Measurement Check and Calibration Setup	4-4
4-4.	Reference Supply and External Kelvin-Varley Divider Check Setup	4-5
4-5.	Voltage Readout Dial Limits	4-6
4-6.	AC to DC Converter Calibration Setup	4-6
4-7.	AC Measurement Check	4-7
4-8.	Adjustment Locations	4-7
4-9.	Troubleshooting Chart (Sheet 1 of 2)	4-10
4-9.	Troubleshooting Chart (Sheet 2 of 2)	4-11
4-10.	Transistor Terminal Locations	4-12
4-11.	Transistor Voltage Chart	4-13
4-12.	Kelvin-Varley Divider Check Setup	4-15
4-13.	Kelvin-Varley Divider Error Limits	4-16
4-14.	Kelvin-Varley Divider Adjustment Setup	4-17
4-15.	Kelvin-Varley "A" Deck Adjustment	4-18
5-1.	Final Assembly (Sheet 1 of 2)	5-5
5-1.	Final Assembly (Sheet 2 of 2)	5-6
5-2.	Front Panel Assembly	5-7
5-3.	Reference Supply Board Assembly	5-10
5-4.	Null Detector Board Assembly (Sheet 1 of 2)	5-13
5-4.	Null Detector Board Assembly (Sheet 2 of 2)	5-14
5-5.	Kelvin-Varley Assembly	5-16
5-6.	Attenuator Assembly	5-18
5-7.	Converter Board Assembly (Sheet 1 of 2)	5-23
5-7.	Converter Board Assembly (Sheet 2 of 2)	5-24



MODEL 883A DIFFERENTIAL AC/DC VOLTMETER

SECTION I

INTRODUCTION AND SPECIFICATIONS

1-1. INTRODUCTION

1-2. This instruction manual is for use with the 883A series Differential AC/DC voltmeters. These are available as either a line-powered instrument (Model 883A) or as a combination line-powered or battery-powered instrument (Model 883AB). Both instruments are half rack size and are equipped with resilient feet and tilt-up bail for field or bench use. A single instrument may be mounted in a standard 19 inch rack by means of metal handle rack adapter kit 881A-102. Two instruments may be mounted side-by-side by means of metal handle rack adapter kit 881A-103.

1-3. The 883A series instruments are capable of being used as conventional voltmeters for rapid determination of voltages from 0 to 1100 volts dc and from 0.001 to 1100 volts ac to within ±3% of range setting, as differential voltmeters for precise measurement of dc voltages from 0 to 1100 volts to within ±(0.01% of input voltage + 5 uv), as an accurate ac voltmeter for measurement of ac voltages from 0.001 to 1100 volts to within ±(0.1% of input voltage + 25 uv) from 20 Hz to 5 kHz and with reduced accuracy from 5 Hz to 100 kHz, and as megohmmeters for measurements of resistance from 10 megohms to 11,000 megohms with a typical accuracy of 5%. They can also be used to measure the excursions of a voltage about some nominal value. One feature that should be emphasized is that no current is drawn from the unknown source at null up to 11 volts dc. Thus the determination of the unknown potential is independent of its source resistance. Above 11 volts dc, the input resistance is an excellent 10 megohms. To minimize errors due to common mode voltages, the 883A series is provided with extremely high leakage resistance to ground --- typically several hundred thousand megohms. Also, where ground loops errors are a problem, the battery operated mode of the 883AB eliminates these errors due to complete isolation from the power line. As additional features, the 883A series contains a polarity switch for equal convenience in measuring positive or negative dc voltages and an adjustable recorder output which makes the instrument particularly useful for monitoring the stability of almost any ac or dc voltage. Furthermore, thorough shock, vibration, humidity, and temperature testing assure years of hard use under severe environmental conditions.

1-4. When used as a dc differential voltmeter, the 883A operates on the potentiometric principal. An unknown voltage is measured by comparing it to a known adjustable voltage with the aid of a null detector. An accurate standard for measurement is obtained from an 11 volt dc reference supply derived from a pair of temperature-compensated zener diodes. The known adjustable reference voltage is provided by a Kelvin-Varley voltage divider with four decades of FLUKE precision wirewound resistors and a high-resolution interpolating vernier that are set accurately by five voltage readout dials to give a six digit readout. In this way, the 11 volts can be precisely divided into increments smaller than 10 microvolts. The unknown voltage is then simply read from the voltage dials. For voltages between 11 and 1100 volts dc, an input attenuator divides the unknown voltage by 100 before it is measured potentiometrically. When used as an accurate ac voltmeter, the 883A operates essentially the same as for dc differential measurements. The ac input voltage is converted to a dc voltage and this dc voltage is measured by comparing it to a known adjustable reference voltage.

1-5. INPUT POWER

1-6. Like most FLUKE instruments, the 883A is normally supplied with dual primary windings connected in parallel for 115 volt line operation. Upon request, the instrument is supplied for 230 volt line operation with the primary windings connected in series. If it becomes desirable to convert from one mode of operation to the other, refer to the instruction decal on the power transformer.

1-7. DAMAGE IN SHIPMENT

1-8. Immediately upon receipt, thoroughly inspect the instrument for any damage that may have occurred in transit. If any damage is noted, follow the instructions outline on the warranty page at the back of this manual.

1-9. SPECIFICATIONS

AS A DIFFERENTIAL VOLTMETER

DC ACCURACY: ± (0.01% of input voltage + 5 uv) over the complete operating conditions listed under general specifications.

DC ACCURACY UNDER CONTROLLED ENVIRONMENT: ± (0.005% of input voltage + 0.0002% of range setting + 5 uv) at 73° F (23° C). Derated at 0.0002%/° F (0.0004%/° C) from 73° F (23° C) between 55° F and 95° F (13° C and 35° C).

AC ACCURACY:

Input Voltage	Basic AC Accuracy		Low Frequency AC Accuracy		High Frequency AC Accuracy	
	20 Hz to 5 kHz	5 kHz to 10 kHz	10 Hz to 20 Hz	5 Hz to 10 Hz	10 kHz to 20 kHz	20 kHz to 100 kHz
0.001 to 1100V	±(0.1% + 25uv)	±(0.15% + 25uv)	±(0.3% + 25uv)	±(1% + 25uv)	–	–
0.1 to 1100	–	–	–	–	±0.3%	–
0.1 to 110	–	–	–	–	–	±1%

AC ACCURACY UNDER CONTROLLED ENVIRONMENT: ± (0.06% of input voltage + 0.002% of range + 25 uv) from 0.001 to 500 volts and ± 0.08% of input voltage from 500 to 1100 volts between 30 Hz and 5 kHz at 73° F (23° C). Derated at 0.0015%/° F from 73° F between 55° F and 95° F (13° C and 35° C).

RANGE:

Voltage Range	Null Range	DC Input Resistance at Null	AC Input Impedance
1	0.1-0-0.1	Infinite	1 Meg, 40 pf
	0.01-0-0.01	Infinite	"
	0.001-0-0.001	Infinite	"
	0.0001-0-0.0001	Infinite	"
10	1-0-1	Infinite	"
	0.1-0-0.1	Infinite	"
	0.01-0-0.01	Infinite	"
	0.001-0-0.001	Infinite	"
100	10-0-10	10 Meg	"
	1-0-1	10 Meg	"
	0.1-0-0.1	10 Meg	"
	0.01-0-0.01	10 Meg	"
1000	100-0-100	10 Meg	"
	10-0-10	10 Meg	"
	1-0-1	10 Meg	"
	0.1-0-0.1	10 Meg	"

NOTE: Each voltage range and each null range has the capability of measuring 10% over voltage.

RESOLUTION:

Voltage Readout Dial Resolution			
Voltage Range	Null Range	Resolution	
		ppm of Voltage Range	Volts
1	any	1 ppm	1 uv
10	"	1 ppm	10 uv
100	"	1 ppm	100 uv
1000	"	1 ppm	1 mv

Meter Resolution (1/2 of a small meter scale division)		
Voltage Range	Null Range	Resolution
any	0.0001	1 uv
"	0.001	10 uv
"	0.01	100 uv
"	0.1	1 mv
"	1	10 mv
"	10	100 mv
"	100	1 v

AS A CONVENTIONAL VOLTMETER

ACCURACY: ± 3% of range from 0 to 1100 vdc and 0.001 to 1100 vac.

RANGE:

Voltage Range	DC Input Resistance	AC Input Impedance
1000-0-1000	10 Meg	1 Meg, 40 pf
100-0-100	"	"
10-0-10	"	"
1-0-1	"	"
*0.1-0-0.1	"	"
*0.01-0-0.01	"	"
*0.001-0-0.001	1 Meg	"
*0.0001-0-0.0001	"	"

*These ranges are obtained by using null ranges with all five voltage dials set to zero.

NOTE: Each range has the capability of measuring 10% overvoltage.

GENERAL

ELECTRICAL DESIGN: Completely solid-state.

INPUT RESISTANCE OF NULL DETECTOR: 10 megohms on two highest null ranges for all input ranges; 1 megohm on two lowest null ranges for all input ranges.

REFERENCE ELEMENT: Temperature-compensated zener diode, stability within ±15 ppm per year, and temperature coefficient less than 2 ppm/° C.

REGULATION OF REFERENCE SUPPLY: 0.0005% for a 10% line voltage change.

STABILITY OF REFERENCE SUPPLY: ±0.001% per hour after 5 minute warmup.

ACCURACY OF OFF-NULL DEFLECTION: ±5% of null range (±3% with voltage dials to zero).

KELVIN-VARLEY ACCURACY: ±0.002% of setting from 1/11 of full scale to full scale. Ratio stability of decade resistors, 10 ppm/year.

RECORDER OUTPUT: Adjustable from 0 to at least +20 mv for full scale right deflection and from 0 to at least -20 mv for full scale left deflection.

POLARITY: Front panel switch selects +DC, -DC, and AC.

WARMUP TIME: DC-15 seconds; AC-1 minute.

COMMON MODE REJECTION: 130 db at dc; 85 db at 60 cps; 70 db at 400 cps. Up to 1000 vdc may be applied between common and ground posts without damage. NOTE: Battery operation of Model 883AB provides complete isolation from power system ground, for elimination of errors due to ground loops.

OPERATING TEMPERATURE RANGE: Within DC specifications from 55° F to 95° F (13° C to 35° C), derated at 0.0004%/° F (0.0007%/° C) outside these limits to 32° F and 122° F (0° C and 50° C).

Within AC specifications from 55° F to 95° F (13° C to 35° C), derated outside these limits to 32° F and 122° F (0° C and 50° C) as follows:
±0.002%/° F (±0.004%/° C) up to 10KC
±0.004%/° F (±0.008%/° C) above 10KC

STORAGE TEMPERATURE RANGE: Model 883A, -40° F to +158° F (-40° C to +70° C); Model 883AB, -40° F to +140° F (-40° C to +60° C).

SHOCK: Meets requirements of MIL-T-945A and MIL-S-901B.

VIBRATION: Meets requirements of MIL-T-945A.

INPUT POWER: Model 883A - 115/230 vac ±10%, 50 - 440 cps; Model 883AB - 115/230 vac ±10%, 50 - 440 cps and rechargeable battery operation (minimum 30 hours operation on full charge).

SIZE: 7" high x 8-1/2" wide 14-3/4" deep.

WEIGHT: Model 883A - approximately 13 lbs.
Model 883AB - approximately 14 lbs.

SECTION II

OPERATING INSTRUCTIONS

2-1. FUNCTION OF EXTERNAL CONTROLS, TERMINALS AND INDICATORS

2-2. The location, circuit symbol, and a functional description of the external controls, terminals, and indicators on the 883A and 883AB Precision Differential DC Voltmeter may be found in figure 2-1 and 2-2.

2-3. PRELIMINARY OPERATION FOR 883A

2-4. The following procedure prepares the Model 883A for operation.

a. Connect power plug to a 115 volt ac power outlet. If instrument has been wired for 230 volt operation, connect to 230 volts ac.

WARNING

The round pin on polarized three-prong plug connects instrument case to power system ground. Use a three-to-two pin adapter when connecting to a two-contact receptacle. For personnel safety, connect short green lead to a good earth ground.



Figure 2-1. LOCATION OF CONTROLS, TERMINALS, AND INDICATORS

INDEX NO.	CONTROLS TERMINALS AND INDICATORS	CIRCUIT SYMBOL	FUNCTIONAL DESCRIPTION
1	INPUT and COMMON terminals	J1, J2	Provided for connecting ac or dc voltage to be measured.
2	Chassis ground terminal	J3	Provided for grounding purposes. A 0.01 uf capacitor is connected from the COMMON binding post to the chassis ground post. The INPUT post should never be connected to the chassis ground post. Since the instrument is equipped with a three-wire line cord with the third wire fastened to the chassis, the circuit should be checked for conflicts in grounding before connecting COMMON binding post to the chassis post.
3	POWER switch	S1	In the Model 883A, the POWER switch applies ac line voltage to primary circuit of transformer when turned from OFF to ON. In the Model 883AB, positions for OFF, BAT CHECK, and three modes of operation (LINE OPR, BAT CHG - LINE OPR, and BAT OPR - LINE ISOL) are available. When set to LINE OPR, ac line voltage is applied to primary circuit of transformer. When set to BAT CHG - LINE OPR, ac line voltage is applied to primary of transformer and batteries are charged at the same time. When set to BAT OPR - LINE ISOL, battery power is applied to the instrument and both sides of primary circuit are open. When set to BAT CHECK, battery power is applied to the instrument, both sides of primary circuit are open, and meter is connected in series with a resistor to measure voltage between reference supply batteries and reference supply output which indicates the condition of the batteries.
4	Electronic ZERO control	R239	A screwdriver adjustment used to zero null detector in the .0001 volt null mode on the 1 volt range and in the .01 volt null mode on the 100 volt range. For best results, input should be shorted prior to zeroing.
5	RANGE switch	S2	Selects desired voltage range, changes null ranges appearing in NULL window, and positions decimal point for voltage readout dials. Voltage ranges of 1, 10, 100, and 1000 volts are available. A voltage 10% higher than range setting may be measured in each range.
6	NULL switch	S3	Set to TVM for determining the approximate value of unknown voltage prior to differential measurements. Seven null voltage ranges (four of which are used for each setting of the RANGE switch) of 100, 10, 1, 0.1, 0.01, 0.001, and 0.0001 volts are used for differential measurements. These ranges represent full scale differences between the unknown voltage and the amount of precision internal reference voltage that is set on the voltage readout dials.
7	A, B, C, D, and E voltage readout dials	S5, S6, S7, S8, R13	Provide an in-line readout of the amount of internal reference voltage necessary to null the unknown voltage.
8	AC-DC polarity switch	S4	Selects the AC, + (dc), or - (dc) mode of operation. With this switch in the positive position, the polarity of INPUT binding post is positive with respect to COMMON binding post.

Figure 2-2. DESCRIPTION OF CONTROLS, TERMINALS, AND INDICATORS (Sheet 1 of 2)

INDEX NO.	CONTROLS TERMINALS AND INDICATORS	CIRCUIT SYMBOL	FUNCTIONAL DESCRIPTION
9	Mechanical zero control	None	Sets meter to zero mechanically. This adjustment should be used only after instrument has been turned off for at least three minutes or when the internal meter terminals have been shorted.
10	Meter	M1	Indicates approximate voltage when 883A is in TVM mode and difference between unknown and internal reference voltage when 883A is in differential mode.
11	RECORDER OUTPUT terminals	J4, J5	Provided for attaching a recorder to monitor voltage excursions.
12	AMP ADJ control	R8	Varies the output level of the output binding post from 0 to at least 20 millivolts at full scale deflection.
13	Fuse	F1	Fuse holder protrudes from instrument to provide easy access to the fuse. The fuse is a 1/16 ampere slow blowing type for 115 volt operation and a 1/32 ampere slow blowing type for 230 volt operation.

Figure 2-2. DESCRIPTION OF CONTROLS, TERMINALS, AND INDICATORS (Sheet 2 of 2)

b. Set switches on 883A voltmeter as follows:

RANGE	1000
NULL	TVM
ac-dc polarity	+ (positive)
all voltage readout dials	0 (zero)
POWER	ON

2-5. PRELIMINARY OPERATION FOR 883AB

2-6. The following procedure prepares the Model 883AB for operation.

a. For line operation, connect power plug to a 115 volt ac power outlet. If instrument has been wired for 230 volt operation, connect to 230 volts ac.

WARNING

The round pin on polarized three-prong plug connects instrument case to power system ground. Use a three-to-two pin adapter when connecting to a two-contact receptacle. For personnel safety, connect short green lead to a good earth ground.

b. For line operation, set POWER switch to LINE OPR.

c. For battery operation, set POWER switch to BAT CHECK. Meter needle should deflect to BATTERY OK region. If meter needle does not stay within BATTERY OK region for 10 seconds, charge batteries as outlined in paragraph 2-9. If batteries are charged, set POWER switch to BAT OPR-LINE ISOL.

d. Set switches on 883AB voltmeter as follows:

RANGE	1000
NULL	TVM
ac-dc polarity	+ (positive)
all voltage readout dials	0 (zero)

2-7. ZEROING INSTRUCTIONS

2-8. From time to time, it may be necessary to adjust the electronic meter zero control. This will normally be done at somewhat more frequent intervals than complete instrument calibration. Proceed as follows:

a. Perform preliminary operation as stated in paragraph 2-3 or 2-5.

b. Mechanically zero the meter with the adjustment screw on the front of the meter case. If the instrument is in the case, it must be shut off for at least three minutes prior to this adjustment. If out of case, another method would be to short out the internal panel meter terminals prior to zeroing.

c. Turn instrument on and allow a 5 minute warmup period.

d. Set RANGE switch to 1, voltage readout dials to zero, and NULL switch to 0.0001.

e. Short INPUT post to COMMON post and adjust electronic ZERO control with a screwdriver for zero meter deflection.

f. Remove short from between INPUT and COMMON post.

2-9. BATTERY CHARGING

a. Connect power plug to a 115 volt ac power outlet. If instrument has been wired for 230 volt operation, connect to 230 volts ac.

b. Set POWER switch to BAT CHG-LINE OPR. After 16 hours, batteries will be fully charged and capable of operating the instrument for at least 30 hours. While

the batteries are being charged, the instrument may be operated the same as for line operation.

CAUTION

Since overcharging decreases battery life, it is recommended that the batteries be charged for less than 48 hours and never more than 1 week. When used properly, the batteries will give more than 200 charge-discharge cycles of operation.

2-10. OPERATION AS A DC DIFFERENTIAL VOLTMETER

a. Perform preliminary operation as stated in paragraph 2-3 or 2-5.
b. Connect unknown voltage between INPUT and COMMON post.
c. Turn RANGE switch to lowest range that will allow an on-scale reading and note approximate value of unknown voltage as indicated on meter scale.
d. If meter reads to left, turn ac-dc polarity switch to negative position. The meter needle will deflect to right. This is because polarity of unknown voltage is negative.
e. Noting position of decimal point, set five voltage readout dials to approximate voltage determined in step c. For example, if voltage is approximately 35 volts, decimal point will be between B and C voltage readout dials. Therefore, set A dial to 3 and B dial to 5.
f. Set NULL switch from TVM to successively more sensitive null ranges and adjust voltage readout dials for zero meter deflection in each null position. When meter needle indicates to the right, magnitude of voltage under measurement is greater than voltage set on voltage readout dials. When indication is to the left, voltage is less than that set on readout dials.
g. Read unknown voltage directly from five voltage readout dials.

2-11. OPERATION AS AN AC DIFFERENTIAL VOLTMETER

a. Perform preliminary operation as stated in paragraph 2-3 or 2-5.
b. Set ac-dc polarity switch to AC.
c. Connect unknown ac voltage between INPUT and COMMON posts. If one side is grounded, always connect it to the COMMON post.
d. Turn RANGE switch to lowest range that will allow an on-scale reading and note approximate value of unknown voltage as indicated on meter scale.
e. Noting the position of the decimal point, set five voltage readout dials to approximate voltage determined in step d. For example, if the voltage is approximately 35 volts, the decimal point will be between the B and C voltage readout dials. Therefore, set A dial to 3 and B dial to 5.
f. Set NULL switch to successively more sensitive null ranges and adjust voltage readout dials for zero meter deflection in each null position. When meter needle indicates to the right, magnitude of voltage under measurement is greater than voltage set on voltage readout dials. When indication is to the left, voltage is less than that set on readout dials.
g. Read unknown voltage directly from the five voltage readout dials.

2-12. OPERATION AS A CONVENTIONAL VOLTMETER

2-13. If it is desired to use the instrument as a conventional 3% voltmeter only, additional ranges can be made available by converting the NULL ranges to conventional voltmeter ranges. This is made possible by setting the voltage readout dials to zero. Proceed as follows:

a. Perform preliminary operation as stated in paragraph 2-3 or 2-5.
b. Consult figure 2-3, and select full scale voltage deflection desired. If approximate value of voltage to be measured is unknown, select the 1000 volt range initially.
c. Set ac-dc POLARITY switch, RANGE switch, NULL switch, and voltage dials as indicated for the range selected.
d. Connect voltage to be measured between INPUT and COMMON posts. If one side is grounded, always connect it to the COMMON post.
e. Read voltage from meter scale. Deflection to right indicates an unknown dc voltage is of positive polarity. An unknown ac voltage will always deflect to the right.

FULL-SCALE DEFLECTION	AC-DC POLARITY SWITCH	RANGE SWITCH	NULL SWITCH	VOLTAGE DIALS
DC:				
1000-0-1000	+	1000	TVM	No effect
100-0-100	-	100	TVM	No effect
10-0-10	+	10	TVM	No effect
1-0-1	+	1	TVM	No effect
0.1-0-0.1	+	1	0.1	All zero
0.01-0-0.01	+	1	0.01	All zero
0.001-0-0.001	+	1	0.001	All zero
0.0001-0-0.0001	+	1	0.0001	All zero
AC:				
0-1000	AC	1000	TVM	No effect
0-100	AC	100	TVM	No effect
0-10	AC	10	TVM	No effect
0-1	AC	1	TVM	No effect
0-0.1	AC	1	0.1	All zero
0-0.01	AC	1	0.01	All zero
0-0.001	AC	1	0.001	All zero

Figure 2-3. VTVM RANGES

2-14. MEASUREMENT OF VOLTAGE EXCURSIONS ABOUT A NOMINAL VALUE

a. Perform preliminary operation as stated in paragraph 2-3 or 2-5.
b. Set ac-dc polarity switch to desired position.
c. Connect voltage to be observed between INPUT and COMMON posts. If one side is grounded, always connect it to the COMMON post. Deflection to the left indicates the voltage being measured is negative dc; set polarity switch to the negative position in this case. This will cause meter pointer to deflect to the right.
d. Set RANGE switch to lowest range which will give an on-scale meter indication and note nominal value of voltage indicated.
e. Set five voltage readout dials to nominal voltage.

f. Turn NULL switch to lowest position that will allow voltage excursions to remain on scale.

g. Read voltage excursions from meter. Note that full scale right and left meter deflections are equal to the NULL range setting (disregarding 10% over-range at end of scale). Meter deflection to the right indicates that magnitude of voltage under observation has increased above the nominal value while deflection to the left indicates it has decreased.

2-15. RECORDING VOLTAGE EXCURSIONS

2-16. Recorder output binding posts and an output level control are provided on the 883A and 883AB for monitoring the excursions of an unknown voltage from the voltage indicated by the voltage readout dial settings. If the leakage resistance between the recorder and ground is less than 10,000 megohms, the accuracy of the voltmeter will be impaired. Therefore, the FLUKE Model A88 Isolation Amplifier is recommended for this application. The A88 will allow the use of a wide range of strip chart recorders for recording the voltmeter reading without regard to the input isolation characteristics of the recorder.

2-17. USE OF 883A WITH AN A88 ISOLATION AMPLIFIER AND A RECORDER

2-18. To use the A88 Isolation Amplifier and a recorder with the 883A or 883AB, proceed as follows:

a. Set A88 POWER switch to ON.

b. When batteries are being used as a power source for A88, measure voltage at BATT TEST jacks. If voltage is between 11.7 and 14 volts DC, the batteries are satisfactory for use. However, if battery voltage is below 12.8 volts, batteries are approaching end of their useful life and should be replaced.

c. Connect RECORDER OUTPUT terminals of differential voltmeter to INPUT terminals of isolation amplifier with teflon leads.

d. Connect OUTPUT terminals of isolation amplifier to recorder input terminals.

e. Perform preliminary operation as stated in paragraph 2-3 or 2-5.

f. Short INPUT post to COMMON post and set switches on voltmeter as follows:

RANGE	10
NULL	1
voltage readout dials	1.00000

The meter will indicate full scale (-1.0). This provides up to a maximum of at least 20 millivolts at RECORDER OUTPUT terminals depending on setting of AMP ADJ control.

g. Turn on recorder and set recorder gain so that a recorder input of either ±2 volts or near maximum if maximum is below ±2 volts, will cause recorder deflection desired for full scale deflection of differential voltmeter.

h. Adjust AMP ADJ control on rear of differential voltmeter until recorder deflection obtained is that desired to correspond to full scale deflection of the differential voltmeter.

i. Remove short from INPUT to COMMON post. The voltmeter and recorder are now ready for recording the measurement of voltage excursions about a nominal value. Proceed as instructed under paragraph 2-14.

2-19. USE OF 883A WITH A RECORDER

2-20. To use a recorder with the 883A or 883AB proceed as follows:

a. Connect RECORDER OUTPUT terminals of differential voltmeter to input terminals of recorder with teflon leads.

NOTE

Do not ground either of the voltmeter RECORDER OUTPUT terminals or either of the recorder input terminals. If any of these terminals are grounded, current will be drawn from the Kelvin-Varley divider and the voltmeter will no longer be accurate.

b. Perform preliminary operation as stated in paragraph 2-3 or 2-5.

c. Check for excessive electrical leakage as follows:

(1) Connect a voltage to the input of the 883A and differentially measure its potential in the most sensitive null range.

(2) Alternately connect and disconnect the recorder leads from the output terminals of the 883A while noting the meter needle deflection. More than one major scale division deflection (10% of null range) indicates that excessive leakage has been introduced by the recorder. This will impair the accuracy of the 883A voltmeter.

(3) Disconnect the voltage.

d. Short INPUT post to COMMON post and set switches on voltmeter as follows:

RANGE	10
NULL	1
voltage readout dials	1.00000

The meter will indicate full scale (-1.0). This provides up to a maximum of at least 20 millivolts at RECORDER OUTPUT terminals depending on setting of AMP ADJ control.

e. Adjust AMP ADJ control until recorder deflection obtained is that desired to correspond to full scale deflection of the voltmeter.

f. Remove short from INPUT to COMMON post. The voltmeter and recorder are now ready for recording the measurement of voltage excursions about a nominal value. Proceed as instructed under paragraph 2-14.

2-21. MEASUREMENT OF HIGH RESISTANCE

2-22. One of the features of the 883A voltmeter is its ability to be used as a megohmmeter for rapid measurements of high resistance from 10 megohms to 11,000 megohms with a typical accuracy of 5%. The following

equation may be used to compute the resistance in megohms of an unknown connected to the input binding posts when the RANGE switch is set to 10:

$$R_X = R_i \quad (\frac{E}{E_m} - 1) \text{ megohms}$$

where:

R_X is the unknown resistance in megohms.

E is the voltage indicated by the voltage readout dials.

E_m is the voltage indicated on the meter.

R_i is the input resistance of the TVM circuit in megohms. 10 for the 1 and 0.1 null range and 1 for the 0.01 and 0.001 null range on the 10 volt range.

2-23. For rapid measurement of resistance between 10 megohms and 11,000 megohms, proceed as follows:

a. Perform preliminary operation, paragraph 2-3 or 2-5.
b. Set RANGE switch to 10 and NULL switch to 1.
c. Connect unknown resistance between INPUT post and COMMON post. Use short isolated leads to prevent measurement of leakage resistance between leads.
d. Adjust voltage readout dials for full scale meter deflection (-1.0). If full scale deflection cannot be obtained with NULL switch set to 1, set NULL switch to 0.1 or 0.001.
e. Determine value of unknown resistance from figure 2-4.

Range of Unknown Resistance	Null Switch Position	To Obtain Value Of Unknown In Megohms When Meter Indicates Full Scale
10 MΩ to 100 MΩ	1	Multiply amount set on voltage readout dials by 10 and subtract 10.
90 MΩ to 1090 MΩ	0.1	Multiply amount set on voltage readout dials by 100 and subtract 10.
1,000 MΩ to 11,000 MΩ	0.001	Multiply amount set on voltage readout dials by 1000.

Figure 2-4. RESISTANCE MEASUREMENTS

2-24. NOTES ON MEASURING AC OR DC VOLTAGES

2-25. GROUND LOOP PRECAUTIONS

2-26. Ground loop currents should be avoided to assure accuracy when making measurements. Potential differences are often found at different points on power system grounds. When this is the case, current may flow from the power system ground through the 883A and the equipment under measurement and back to the power system ground. To avoid this when system being measured is grounded, do not connect 883A COMMON binding post to chassis ground post.

2-27. USE OF SHORTING LINK

2-28. A 0.01 uf capacitor (C1) is connected from the COMMON binding post to the chassis ground post to reduce the effect of circulating ac currents from the transformer. In some cases, it is possible for C1 to acquire a charge. For example, C1 will become charged when making common mode voltage measurements. This condition may cause an error on low level measurements (under 5 volts) due to C1 discharging through the Kelvin-Varley divider and leakage resistance to ground. Connecting the shorting link from the COMMON post to the ground post for a few seconds will discharge C1 and thus prevent an inaccurate indication.

2-29. BATTERY CHECKING

2-30. If the voltmeter is left in the battery operating mode for an extended period of time, the batteries will become discharged. When the batteries are left in a completely discharged state with the voltmeter turned off, their voltage will recover with time. It is possible that the batteries may have recovered enough for the meter to indicate they are charged when the power switch is first set to battery check. However, after a few seconds, the battery voltage will fall and the meter will indicate that the batteries need to be charged. It should also be noted that the voltage characteristic of the nickel-cadmium batteries is very flat except near full charge and complete discharge. Therefore, when the batteries are checked, the meter needle deflection will not be proportional to the remaining ampere-hour capacity of the batteries. Just after the batteries are charged, the meter needle will indicate near full scale. However, most of the time the batteries are charged, the meter needle will indicate near half scale. A few hours before the batteries need a recharge, the meter needle will indicate just within the battery ok region.

2-31. EFFECT OF COMMON MODE VOLTAGES

2-32. Common mode errors are caused by leakage currents passing through ground loops. Since great care has been taken in the design and construction to insulate the circuitry from chassis ground, accurate dc common mode measurements up to 1000 volts dc above ground can be made with the 883A and 883AB. The dc common mode rejection is at least 134 db (5,000,000 to 1) or 0.2 uv error per common-mode-volt all the way up to 70% relative humidity. However, since the leakage resistance is dependent on dampness, the dc common mode error is typically much less at lower relative humidities. Thus, common mode measurements should be made with a relative humidity below 70%. Also, if the common mode voltage is greater than 50 volts, the measurement should be made several minutes after hookup for best accuracy. This is due to the time it takes to charge stray capacities to ground through the extremely high leakage resistances.

2-33. NOTES ON MEASURING DC VOLTAGES

2-34. EFFECT OF AC COMPONENTS ON DC MEASUREMENTS

2-35. An ac component of several times the unknown dc may be present on the unknown and the 883A will always indicate well within the specifications for frequencies

over a few hundred cycles. An ac component may have an adverse effect if it is of a low frequency or if it has a frequency that is a multiple or submultiple of the chopper frequency. A triple section low pass filter (R201, C201, R202, C202, R203, and C203) is used at the input of the null detector to reduce any ac present on the dc being measured. At lower frequencies, this low pass filter is less effective and the magnitude of the ac component is more significant. If this frequency is below 100 Hertz, the accuracy may no longer be with specifications. For example, a 60 Hertz ac voltage that is 1% of the input will cause an error of approximately 0.001% which is well within the specifications. This 1000:1 rejection of ac also applies until the ac voltage is 1000 times the null range. For example, on the .01 volt null range, the ac rejection of 1000:1 applies up to 10 vac. When the frequency is very close to a multiple or submultiple of the chopper frequency (approximately 84 Hertz), the meter needle will oscillate at the difference frequency. If ac components that affect the accuracy are ever encountered, additional filtering will be required. For an ac of a single frequency, a twin-T filter is effective and has the advantage of low total series resistance. For an ac variable frequency, an ordinary low pass filter may be used. In either case, high quality capacitors of high leakage resistance should be used.

2-36. MEASUREMENT OF NEGATIVE VOLTAGES

2-37. Because of a polarity switch, voltage which are negative with respect to ground as well as the more commonly encountered positive voltages may be measured with equal facility. If the INPUT post is connected to the metal case, either at the 883A or at the source under measurement, the accuracy of the voltmeter may be reduced. However, with the polarity switch, the INPUT post never has to be connected to ground. If the unknown voltage is grounded, always connect the grounded side to the COMMON post and use the polarity switch to obtain the proper result.

2-38. NOTES ON MEASURING AC VOLTAGES

2-39. ERRORS DUE TO DISTORTION

2-40. The ac to dc converter in the 883A is an average measuring device calibrated in rms. The converter will put out a dc voltage that is proportional to 1.11 times the average value of the ac input voltage. Thus, if the input signal is not a true sinusoid, the 883A reading is probably in error because the ratio of rms to average is usually not the same in a complex wave as in a sine wave. The magnitude of the error is dependent on magnitude of the distortion and on its phase and harmonic relationship with respect to the fundamental. Figure 2-5 indicates how the accuracy will be affected by various harmonics for different percentages of distortion. If the distortion present in the signal is composed of even harmonics and is less than 2%, the error between the 883A reading and true rms is minor. A larger error can occur if the distortion is composed of odd harmonics, especially the third harmonic. Note that for 2% of third harmonic distortion the error in the reading could range from 0 to 0.687%.

Harmonic	% Distortion	% Error From True RMS*	
		Maximum Positive	Maximum Negative
Any even harmonic	0.1	0.000	0.000
	0.5	0.000	0.0001
	1.0	0.000	0.005
	2.0	0.000	0.020
Third harmonic	0.1	0.033	0.033
	0.5	0.167	0.168
	1.0	0.328	0.338
	2.0	0.667	0.687
Fifth harmonic	0.1	0.020	0.020
	0.5	0.099	0.101
	1.0	0.195	0.205
	2.0	0.380	0.420

*Error depends upon phase relationship between harmonic and fundamental, i. e. error can be any value between maximum positive and maximum negative, including zero.

Figure 2-5. PERCENT ERROR DUE TO HARMONIC DISTORTION

2-41. ERRORS DUE TO GROUNDING

2-42. In the 883A there is a 0.01 uf capacitor connected from the COMMON terminal (middle post) to chassis ground. If it is desired to make measurements where the voltage to be connected to the lower input terminal is not at ground potential, a line cord adapter must be used to isolate the 883A chassis from line ground. Otherwise, the 0.01 uf capacitor would place an ac load on the circuit being measured.

2-43. INTERNAL CONVERTER NOISE

2-44. When the instrument is shorted in the ac mode, the converter may produce a residual noise output of approximately 100 uv. This noise voltage will cause an insignificant error as long as ac input signals of 1 mv or larger are applied to the instrument. Figure 2-6 shows a typical half wave of the signal voltage at the output of the converter amplifier. It is easily seen that the noise contributes very little to the average value of the signal and is well within the 2.6% accuracy of the instrument at 1 mv. Also for input signals over 1 mv, the instrument is noise free to within 2 parts per million of the input range. For example, on the 1 volt input range the instrument will contribute less than 2 uv of noise to any measurement.



Figure 2-6. SIGNAL VOLTAGE WITH CONVERTER NOISE

2-45. MOST SENSITIVE NULL RANGE ON AC

2-46. The most sensitive null range for each input range should be used with caution when measuring ac voltages. Most ac sources are not stable enough to be used on this range. For example, if 1.0 volt is measured with the range switch set to 1 and the null switch set to 0.0001, the null detector sensitivity is 100 microvolts full scale. Since 100 uv is 0.01% of 1.0 volt, an ac source with a stability worse than ±0.01% will cause the 883A meter pointer to swing from one end of the meter scale to the other. Also, if the input is shorted with the range switch set to 1 and the null switch set to 0.0001, the meter needle may deflect more than full scale due to converter noise. However, as pointed out in paragraph 2-43, converter noise will not impair the accuracy for input signals greater than 1 mv. Thus, any excessive erratic meter needle movement is due to ac source stability.

SECTION III

THEORY OF OPERATION

3-1. INTRODUCTION

3-2. Figure 3-1 shows the block diagram for the 883A Differential Voltmeter. As seen in this figure, the circuit is mainly composed of an ac to dc converter, a dc input attenuator, a dc transistorized voltmeter (tvm), and an extremely accurate 0 to 11 volt reference. The dc input attenuator reduces the input voltage by a factor of 100 on the 1000 and 100 volt dc range. The tvm uses a null detector, an attenuator, and a meter to obtain high sensitivity. The 0 to 11 volt reference uses a range divider and a Kelvin-Varley attenuator to make the output of two well regulated zener diodes adjustable. Refer to the functional schematic following Section VI for more detail. This schematic is designed to aid in the understanding of circuit theory and troubleshooting. The signal flow is from left to right and the components are laid out in a functionally logical manner.



Figure 3-1. 883A DIFFERENTIAL VOLTMETER BLOCK DIAGRAM

3-3. The overall operation of the voltmeter may be summarized as follows. To measure the approximate value of a dc voltage between 0 and 11 volts, the unknown voltage is connected directly across the tvm attenuator. This attenuator is set in such a way that the maximum voltage for each range is reduced to a signal of 1 millivolt (100 microvolts for the 1 volt range in the highest null mode). The signal is then applied to the null detector and causes 100 microamperes to flow through the meter for full scale deflection. To accurately measure this dc voltage, the unknown voltage is connected across the series combination of the tvm and the 0 to 11 volt reference. The reference voltage is then adjusted with the five voltage readout dials until it matches the unknown voltage as indicated by the tvm. For voltages between 11 and 1100 volts, the dc input attenuator divides the unknown voltage by 100. The 883A then operates essentially the same as for measurements from 0 to 11 volts. All ac measurements are made by first converting the ac input voltage to a dc voltage by means of the ac to dc converter. The 883A then operates essentially the same as for approximate and accurate dc measurements.

3-4. In order to provide for a more complete understanding of the 883A voltmeter, the following paragraphs describe each section of the circuit in detail.

3-5. DC INPUT ATTENUATOR

3-6. Since the instrument contains a 0 to 11 volt reference, the unknown voltage is measured by comparing it to a known voltage with the aid of a null detector only on the 1 and 10 volt range. On the 100 and 1000 volt range, the dc input attenuator (R100 through R104) divides the unknown voltage by 100 and this attenuated voltage is then measured by the potentiometric principal. Thus, after attenuation by 100, the 100 and 1000 volt ranges are reduced to the equivalent of 1 and 10 volt ranges. The dc input attenuator is extremely accurate and has excellant long term stability. The 10K variable resistor (R103) is used during factory calibration to setup the proper division ratio. This adjustment can then be performed as required at regular calibration intervals.

3-7. DC TRANSISORIZED VOLTMETER

3-8. GENERAL

3-9. The dc tvm is composed of an attenuator, a null detector, and meter. The heart of the dc tvm is the null detector in which the dc signal is modulated by an electromechanical chopper, amplified by a five stage resistance-capacitance coupled amplifier, rectified by a transistor switch, and finally filtered to produce a dc output. The null detector has a high amount of negative current feedback. This makes the proportion of the output current feedback approximately equal to the signal voltage divided by the resistance of the feedback resistor, regardless of the amplifier characteristics. The high negative feedback also makes the amplifier relatively insensitive to the gain changes in individual transistors due to aging, and replacement. The output current from the null detector is indicated on a meter that has tautband suspension. This suspension does away with all friction associated with meter pivot stickiness. Thus, any tendency for the meter pointer to stick at one point of the scale and then jump to another point is eliminated. The tvm attenuator is used to reduce the voltage span of each range to a common range usable by the null detector to produce proper meter deflection.

3-10. NULL DETECTOR

3-11. The null detector is a current feedback amplifier that drives a meter. Any feedback amplifier is essentially a null seeking device. That is, it tends to make the voltage fed back to the input equal to the input voltage. In a current feedback amplifier, the feedback voltage is equal to the voltage drop across a fixed resistor caused by the output current or a portion of the output current. At the input to the 883A null detector R201, C201, R202, C202, R203, and C203 form a triple section low pass filter that reduces any ac component present on the dc voltage being measured. The difference between the voltage appearing at the output of the filter and the voltage developed across feedback resistor R236 is converted to an alternating voltage by G201, an 84 hertz chopper. The voltage across R236 is proportional to the current flowing in the meter. The alternating voltage created by G201 is amplified by a five-stage solid-state amplifier. The first stage is a p-channel field effect transistor (Q201). The field effect transistor provides both high impedance and low noise input characteristics. The next four stages consist of two transistor doubletons (Q202 to Q205). During one portion of the chopper cycle, the output of the amplifier is clamped to approximately null detector common potential by Q206, a transistor switch. The transistor switch is gated in synchronization with the chopper since the gating pulse comes from the voltage that is used to drive the chopper. During the other portion of the chopper cycle, the output of the amplifier is filtered by R-C filter R225-C219 to provide a dc current for the meter. A portion of the current that flows through the meter is shunted back to the 200Ω feedback resistor R236 thus completing the feedback loop. The null detector has a basic sensitivity of 1 millivolt except in the most sensitive null mode for the 1 and 100 volt range where the sensitivity is 100 microvolts. For the two most sensitive null modes in the 100 and 1000 volt range, the sensitivity is boosted 10% to compensate for the loading effect of the tvm attenuator on the dc input attenuator. The output resistance of the dc input attenuator is 100K and the input resistance of the tvm dc attenuator is 1 meg. Thus, when monitoring voltage excursions, much more accurate off null readings are obtained due to the 10% boost in null sensitivity.

3-12. TVM ATTENUATOR

3-13. In the dc tvm mode, two positions on the tvm attenuator selected by range switch section S2H provide the necessary reduction of the 1 and 10 volt ranges for proper null detector input. The same two positions on the tvm attenuator are used for the 100 and 1000 volt ranges because the input attenuator divides the input signal by 100 and thus reduces the 100 and 1000 volt ranges to the equivalent of 1 and 10 volt ranges. In the differential mode, the voltage difference (unknown voltage, or unknown voltage divided by 100, minus reference voltage) is reduced as necessary by positions on the tvm

attenuator selected by null switch sections S3H, S3G, and S3E to provide the basic null detector inputs of 1 millivolt or 100 microvolts.

3-14. In the ac tvm mode, null switch section S3H and ac-dc polarity switch section S4E provide connection to only one position on the tvm attenuator regardless of where the range switch is set. Also, in the ac differential mode, the voltage difference (converter output voltage minus reference voltage) is reduced by the same positions on the tvm attenuator as for 1 volt dc differential measurements. This is because the output of the ac-dc converter is 1 volt dc for full input on each range.

3-15. INPUT RESISTANCE

3-16. For the tvm, low sensitivity, and medium low sensitivity modes, the input resistance of the tvm attenuator is 10 megohms (R4 through R7). For the medium high and high sensitivity modes, the input resistance of the tvm attenuator is 1 megohm (R4 through R7). However, this is not the input resistance of the 883A for the dc tvm and dc differential mode. For the 1 and 10 volt range, the input resistance is determined by dividing the unknown voltage by the current drawn from the unknown. The current drawn from the unknown is equal to the difference between the unknown terminal voltage and the internally known voltage divided by the resistance of the tvm attenuator. The equation for input resistance can therefore be written as:

$$R_{in} = \frac{E_u}{I_u} = \frac{E_u R_a}{|E_u - E|} = \frac{E_S (R_a + R_S)}{|E_S - E|} - R_S$$

where:

R_{in} = input resistance of voltmeter

E_u = $E_S - I_u R_S$ = terminal voltage of unknown

I_u = current drawn from unknown

E_S = source voltage of unknown

R_S = source resistance of unknown

R_a = input resistance of tvm attenuator

E = voltage indicated by voltage readout dials

$| \ |$ = absolute value (magnitude only)

Thus, the input resistance is essentially infinite (leakage resistance across input is in the order of 10^{12} ohms) at null when E is equal to E_u and E_S. For the 100 and 1000 volt range, the dc input attenuator is always connected across the input terminals. Thus, the input resistance is equal to the resistance of the dc input attenuator which is 10 megohms.

3-17. The input impedance for the ac tvm and ac differential mode depends on the input impedance of the ac to dc converter and its attenuator. The ac input impedance is thus 1 megohm and 40 picofarads.

3-18. CHOPPER DRIVE CIRCUIT

3-19. The chopper drive circuit determines the chopper timing frequency of 84 Hz. The circuit is symmetrical with the transistors biased so that they can conduct simultaneously. However, cross-coupling capacitors C105 and C106 force Q106, Q109 and Q107, Q108 to conduct alternately. This results in a square wave varying from about 0 to 6 volts that drives chopper coil G201. The symmetry and frequency of the waveform are adjusted with R125 and R123 respectively.

3-20. NULL DETECTOR POWER SUPPLY

3-21. The voltage for null detector amplifier stages Q201 through Q205 is supplied by the same -18 volt power supply that is used to power the 0 to 11 volt reference. The voltage for chopper drive circuit transistors Q106 through Q109 is obtained from a half-wave rectifier consisting of diode CR101 and an R-C vilter network (R105 and C101) that supplies 6 volts dc. Current determining resistors R238 and R240, diodes CR201 and CR202, and divider resistor R239 provide a compensating voltage for the purpose of adjusting the null detector to zero with R239 when there is no signal input. Diode CR201 keeps one side of R239 at approximately +0.6 volt dc with respect to the null detector common while diode CR202 keeps the other side at approximately -0.6 volt dc.

3-22. EFFECT OF AC COMPONENTS ON DC MEASUREMENTS

3-23. The only ac voltage component that will reduce the accuracy of the 883A is one that either saturates the null detector or one that beats with the chopper frequency. Since the voltage required for saturation is greater than that required for beating, the null detector is most sensitive to an ac component with a frequency that is a submultiple or a low multiple of the chopper frequency. However, this is easy to detect because the meter will beat at the difference frequency. The low pass filter at the input of the chopper-amplifier will attenuate any ac component. The magnitude of the ac voltage appearing at the output of the filter depends on both its amplitude and frequency before filtering. For all practical purposes, one should never encounter any trouble above a hundred cycles. Below this, the filter may not attenuate the ac component enough. However, this is not as bad as it appears. A 60 cycle ac voltage that is 1% of the input voltage will cause an error of approximately 0.001% which is well within specifications. If ac components that affect accuracy are ever encountered, additional filtering as set forth in the operating instructions will eliminate the problem.

3-24. TVM GAIN AND ZERO ADJUSTMENTS

3-25. Variable resistor R239 in the feedback network provides a means of adjusting the output current of the null detector to zero when there is no input signal. The gain of the null detector is adjusted by means of R230 in the feedback network for the 1 millivolt sensitivity and by means of R231 for the 100 microvolt sensitivity.

3-26. RECORDER OUTPUT

3-27. The recorder output is picked off divider string R226, R8, and R227. Recorder output AMP ADJ control R8 provides a means of adjusting the output voltage up to a maximum of at least 20 millivolts at full scale deflection (disregarding 10% over-range at end of scale). The voltage at the RECORDER OUTPUT terminals is proportional to the meter reading.

3-28. **0 TO 11 VOLT REFERENCE**

3-29. GENERAL

3-30. When the 883A is used to make differential dc voltage measurements between 0 and 11 volts, an internal voltage is nulled or matched against the unknown voltage. An extremely accurate reference is therefore required. This is obtained from the 0 to 11 volt reference. The 0 to 11 volt reference is composed of a well regulated -18 volt power supply, a range divider, and a five decade Kelvin-Varley divider. The range divider reduces the voltage from a pair of stable Zener diodes in the -18 volt reference supply to 11 volts for the 10 and 1000 volt dc ranges and to 1.1 volts for the 1 and 100 volt dc ranges before it is applied to the Kelvin-Varley divider. The Kelvin-Varley divider divides its input voltage (11 or 1.1 volts) into over 1,100,000 equal increments any number of which may be selected by setting the five decades with the five voltage readout dials. The output of the Kelvin-Varley divider, therefore, provides an extremely accurate reference voltage.

3-31. -18 VOLT POWER SUPPLY

3-32. The -18 volt power supply uses a diode (CR102) and a filter network (R106 and C102) to supply unregulated dc voltage to series passing transistor Q101. In the Model 883AB, unregulated dc is supplied directly from a set of two batteries (BT3) in the BAT CHECK and BAT OPR modes. The voltage is regulated by comparing a sample of the output voltage tapped off a divider string (R108, R109, and R110) with the voltage from Zener reference diodes CR103 and CR104 in differential amplifier Q102 - Q103. The output of Q102 - Q103 is fed to differential amplifier Q104 - Q105 which drives the base of series pass transistor Q101. The control action of the differential amplifiers continuously adjusts the voltage drop across the series pass transistor so as to keep the sample voltage equal to the voltage of the Zener reference diodes. Any difference in voltage, the error, is amplified by Q102 - Q103 and Q104 - Q105 and thus changes the voltage drop across Q101 to maintain the output at -18 volts. The -18 volt output is used to provide operating voltages for the null detector and, with the aid of current determining resistors R115 and R116, to supply an extremely constant current to its own Zener reference diodes CR103 and CR104. The voltage across the two Zener diodes may be anywhere between approximately 11.4 and 13 volts. However, this voltage has a stability of better than ±15 ppm per year and an overall temperature coefficient of less than 2 ppm per °C.

3-33. RANGE DIVIDER

3-34. In the 1000 and 10 volt dc range, the Zener reference diode voltage is connected directly to the Kelvin-Varley divider through resistors R118 and R119 by means of range switch sections S2J and S2I. The voltage drop across R118 and R119 reduces the Zener reference voltage to 11 volts at the input of the Kelvin-Varley divider. In the 100 and 1 volt dc range, range resistors (R120, R121, and R122) selected by range switch sections S2J and S2I reduce the voltage to 1.1 volts at the input to the Kelvin-Varley divider. With the ac-dc switch set to AC, ac-dc switch section S4H provides connection to the range resistors that divide the reference voltage to 1.1 volts. This 1.1 volts is then passed to the Kelvin-Varley divider by ac-dc switch section S4G. The voltage applied to the Kelvin-Varley divider is always 1.1 volts for ac because the maximum output of the ac to dc converter is always 1.1 volts.

3-35. KELVIN-VARLEY DIVIDER

3-36. The five Kelvin-Varley decades composed of resistors R13 and R302 to R364, and associated voltage dials A through E provide a means of making the two precision voltages (11 and 1.1 volts) adjustable. The first decade has twelve 5K resistors (a 4,999.2 ohm resistor and a 2 ohm trimmer). Two of these resistors are shunted by the 10K total resistance of the second decade. Between the two wipers of S5 (voltage dial A) then, there is a total resistance of 5K (10K paralleled by 10K). Thus, the first decade divides the voltage across it into eleven equal parts with one of the equal parts appearing across the two shunted resistors. Similarly, the second, third, and fourth decades divide the voltage across them into ten equal parts. Note that the second, third, and fourth decades each have eleven 1K resistors. The resistors may have the same value because padding resistors R328 - R329 and R315 - R316 are used across the third and fourth decades respectively to keep the proper resistance matching. The last decade, with its associated shunt resistors to keep the proper matching, is a variable resistor which can be set to pick off increments equal to less than 1/100 times the voltage across its input. The Kelvin-Varley resistors are matched for both temperature coefficient and tolerance thus providing an overall accuracy of 0.002% absolute from 1/11 of full scale to full scale. With the null switch in any null range, the output of the Kelvin-Varley divider is connected in series with the tvm attenuator thus providing the accurate 0 to 11 volt or 0 to 1.1 volt reference voltage required.

3-37. ADJUSTMENTS

3-38. Variable resistor R110 is used during final factory calibration to set the reference supply to -18 volts. This adjustment is not exceedingly critical and should have to be done only when a component of the reference supply has been replaced. The voltage from the Zener reference diodes is reduced to 11 volts at the input to the Kelvin-Varley divider by adjusting variable resistor R119 during calibration. Range-divider variable resistor R121 may then be adjusted for 1.1 volts at the input to the Kelvin-Varley divider. The 2 ohm trimmer resistors (even resistors from R342 to R364) and variable padding resistors R329, R316, and R303 should require adjustment only after a component of the Kelvin-Varley divider has been replaced.

3-39. AC TO DC CONVERTER

3-40. GENERAL

3-41. The ac to dc converter is composed of an attenuator, an operational amplifier, and a rectifier-filter circuit. A pair of diodes in the rectifier-filter circuit are used to convert the unknown ac into pulsating dc. This pulsating dc is then filtered to obtain a dc voltage that is proportional to the average value of the ac input voltage. The output, however, is calibrated to indicate the rms value of a pure sine wave. An operational amplifier with high negative feedback is used to make the rectification characteristics of the diodes linear and stable. The first stage is an n-channel field effect transistor (Q501). The field-effect transistor provides both high impedance and low noise input characteristics. The next four stages consist of two transistor doubletons (Q502, Q503, Q504, and Q506). Transistor Q505 acts as a dynamic load and thus increases the output impedance of the amplifier. The amplifier achieves a midband loop gain of approximately 70 db with a virtually flat frequency response from 20 Hz to 20 kHz. At the output of the amplifier, full wave rectification is used to return negative feedback to the gate of the field-effect transistor. The high negative feedback makes the amplifier practically noise free and relatively insensitive to gain changes in individual stages due to aging and transistor replacement. An attenuator is used to reduce the ac input voltage on the higher ranges to within the operating level of the converter amplifier.

3-42. OPERATION

3-43. All ac measurements are made by first converting the ac input voltage into a dc voltage. The converter provides a dc output of 1 volt when full range voltage is applied to the 883A in each ac range. In the 1 volt ac range, the ac-dc polarity switch and the range switch connect the input binding posts directly to the converter input. The converter gain is of such a value that the dc output voltage is equal to the rms value of the converter input voltage for a sine wave. For the 1000, 100, and 10 volt ac ranges, a separate input attenuator for each range reduces the unknown ac voltage by a factor of 1000, 100, and 10 respectively. The operation of the converter is then the same as for the 1 volt range. Thus, an output of 1 volt dc is provided for full range input of a pure sine wave on any ac range.

3-44. ADJUSTMENTS

3-45. The converter gain is adjusted with R503 in the feedback loop of the operational amplifier. Capacitor C502 in the feedback loop is used to adjust the high frequency response of the converter. The attenuation of the 1000, 100, and 10 volt attenuators are adjusted with R410, R406, and R403 respectively. Capacitors C405, C403, and C401 are used to adjust the high frequency response attenuators. The bias of field-effect transistor Q501 should require adjustment with R508 only when Q501 or a component in its drain-source circuit is replaced. The amplifier output level at the collector of Q506 should require adjustment with R522 only if Q505, Q506, or a component in one of these stages is replaced.

3-46. AC-DC POLARITY SWITCH

3-47. The ac-dc polarity switch is provided for selecting either the ac or dc mode of operation. When the ac-dc polarity switch is set to AC, the ac to dc converter is switched into the circuit by sections S4A, S4B, S4C, and S4D. Also, sections S4H and S4G are used to switch 1.1 volts dc to the Kelvin-Varley divider. Section S4E is used to provide proper attenuation in the tvm attenuator.

3-48. For the dc mode of operation, the ac-dc polarity switch may be set to the positive or the negative dc position. As seen in figure 3-2, the polarity switch reverses the transistorized voltmeter - reference voltage combination with respect to the input. Note that a 0.01 uf capacitor (C1) is connected from the COMMON post to the chassis ground post to reduce the effect of ac circulating currents. If the instrument did not contain a polarity switch, the grounded side of any unknown voltage that is negative with respect to ground would have to be connected to the INPUT post. This would ground the INPUT post and effectively place C1 across the input. With this capacitance connected across the circuit being measured several problems would arise. The polarity switch provides equal convenience in measuring positive and negative voltages without the occurance of these problems.



Figure 3-2. FUNCTION OF POLARITY SWITCH

SECTION IV

MAINTENANCE

4-1. INTRODUCTION

4-2. The 883A AC/DC Differential Voltmeter seldom requires any maintenance. Without extreme abuse, all that should be required is periodic cleaning and calibration as specified in this section. However, to determine if the instrument is within specifications, it is recommended that its performance be checked just before calibration by using the performance checks given in this section. If a problem arises, the information on corrective maintenance in this section will be extremely useful.

4-3. TEST EQUIPMENT

4-4. Figure 4-1 lists the recommended equipment and specifications required for performance checking, calibration, and corrective maintenance. If the recommended equipment is not available, other equipment which meets the required specifications may be used.

4-5. PERIODIC MAINTENANCE

4-6. Periodic maintenance consists primarily of occasional cleaning to remove dust, grease, and other types of contamination. However, since the 883A is a completely enclosed unit, the need for occasional cleaning is greatly reduced. Special care has been taken to prevent leakage across critical switch wafers, areas of some printed circuit boards, and from the printed circuit boards to chassis ground. The power, range, null, polarity, and all voltage readout dial switches are vacuum impregnated with Dow Corning silicone oil. These switches are also isolated from the front panel with Lexan spacers. The printed circuit boards are coated with Epocast 8267. Also, the printed circuit boards are isolated from chassis ground by means of polyethelene grommets.

4-7. To prevent excessive electrical leakage, proceed as follows:

CAUTION

Avoid touching polyethelene grommets. The grease on the hands of some people can cause excessive electrical leakage.

a. Blow instrument out with low-pressure, clean, dry air to remove most accumulations of dust and foreign matter. Pay particular attention to the input binding posts, binding post wiring, switches, and polyethelene grommets which insulate printed circuit boards from chassis.

b. Clean polyethelene grommets, binding posts, and front panel with anhydrous denatured ethyl alcohol or a pressure can of Freon TF Degreaser (Miller-Stephenson Chemical Co., Inc.) and, when necessary, a clean cloth or a cotton swab.

CAUTION

Do not use Metriclene, acetone, lacquer thinner, or any other methyl ethyl ketones, since they will react with the Lexan rotor on the CTS plastic switches. Also, be careful not to saturate the switch contacts which have been lubricated for life.

c. When necessary, clean all exposed dielectric surfaces of switches with denatured alcohol using a small, stiff-bristled brush which has been wrapped with a clean cloth to prevent saturating the switch contacts.

d. After cleaning, recoat exposed switch insulating material with a solution of Dow Corning 200 having a viscosity between 5 and 20 centistokes. This prevents leakage due to moisture on these surfaces.

4-8. PERFORMANCE CHECKING

4-9. GENERAL

4-10. The following performance checks are designed to check the instruments performance against the specifications. As such, they may be used as a routine maintenance procedure and as an incoming inspection procedure. They should be accomplished under typical laboratory conditions in a draft free area with an ambient temperature of 72.5 (±2.5)°F. It is recommended that these performance checks be done just before calibration of the instrument. When used in this way, the performance checks yield a valuable case histroy on the characteristics of each individual instrument. Just prior to calibration, the instrument should be within specifications. If the instrument is out of specifications, the error should not be calibrated out of the instrument. The correct procedure is to find the reason why and then eliminate it. Localizing the problem to a particular area of the instrument may be done by an analysis of the performance check results.

NOMEN-CLATURE	SPECIFICATIONS REQUIRED	RECOMMENDED INSTRUMENT	USED FOR	PARA
VTVM	Range: 0 to 40 vdc, 0 to 300 vac Accuracy: ±3% dc, ±5% ac Input Impedance: 10MΩ 5 pf dc 1MΩ, 100 pf ac	RCA Voltohmyst	CORRECTIVE MAINTENANCE -Voltage Level Checking -Reference Voltage Regulation Check -Null Detector Input Stage Bias Adjustment -Converter Input Stage Bias Adjustment -Converter Output Adjustment	 4-44 4-48 4-56 4-58 4-59
Autotransformer	103 to 127 volts (207 to 253 volts for 230 volts nominal line instruments)	General Radio Model W5MT3 Variac (W5HMT for 230 volts nominal line instruments)	CORRECTIVE MAINTENANCE -Reference Voltage Regulation Check	 4-48
DC Differential Voltmeter	Range: 10 to 20 vdc Accuracy: 0.05% Null Range: At least 10 mv.	Almost any FLUKE Differential Voltmeter	CORRECTIVE MAINTENANCE -Voltage Level Checking -Reference Voltage Regulation Check -Negative 18 Volt Supply Adjustment -Converter Supply Adjustment	 4-44 4-48 4-54 4-57
Standard Cell Bank	Accuracy: ±0.0005%	Guildline Instruments Model 9152/P4	PERFORMANCE CHECKING -DC Differential Measurement Check CALIBRATION -DC Preliminary Calibration CORRECTIVE MAINTENANCE -Common Mode Measurement Check	 4-13 4-22 4-49
Power Supply	Voltage: 1 to 1100 vdc Current: 0 to 2 ma Stability: ±0.005% per hour Resolution: 5 mv	FLUKE Model 412B	PERFORMANCE CHECKING -DC Differential Measurement Check CALIBRATION -DC Preliminary Calibration CORRECTIVE MAINTENANCE -Common Mode Measurement Check -Kelvin-Varley Divider Check -Kelvin-Varley Divider Adjustment	 4-13 4-22 4-48 4-51 4-60
Null Detector	Range: 1 uv to 1 mv end scale	FLUKE Model 845A	PERFORMANCE CHECKING -DC Differential Measurement Check CALIBRATION -DC Preliminary Calibration CORRECTIVE MAINTENANCE -Kelvin-Varley Divider Check -Kelvin-Varley Divider Adjustment	 4-13 4-22 4-51 4-60

Figure 4-1. TEST EQUIPMENT REQUIREMENTS (Sheet 1 of 2)

NOMEN-CLATURE	SPECIFICATIONS REQUIRED	RECOMMENDED INSTRUMENT	USED FOR	PARA
Kelvin-Varley Divider	Number of Decades: Seven Input Resistance: 100K Ratio Accuracy: 1 ppm from 1/10 of full scale to full scale	FLUKE Model 720A	PERFORMANCE CHECKING -Differential Measurement Check CORRECTIVE MAINTENANCE -Kelvin-Varley Divider Check -Kelvin-Varley Divider Adjustment	 4-13 4-51 4-60
Lead Compensator	Resolution: 10 mΩ Divider Resistance Ratios: From 1:1 to 10:1	FLUKE Model 721A	CORRECTIVE MAINTENANCE -Kelvin-Varley Divider Check -Kelvin-Varley Divider Adjustment	 4-51 4-60
Voltage Reference Divider	Input Voltage: 10, 100, 1000 vdc Output Voltage: 1, 10, 100, 1000 vdc Accuracy: ±0.001% + 2 uv Divider Current Adjustment Range: To a minimum of 1 ppm and a maximum of 5 ppm on all ranges	FLUKE Model 750A	PERFORMANCE CHECKING -DC Differential Measurement Check CALIBRATION -DC Preliminary Calibration	 4-13 4-22
Oscilloscope	Sweep Range: 1 msec/cm to 10 msec/cm Sensitivity: 2 v/cm	Hewlett Packard Model 120B	CORRECTIVE MAINTENANCE -Chopper Drive Circuit Adjustment	 4-55
Voltage Standard	Voltage: 1 to 1000 vdc Current: 0 to 6 ma Stability: ±0.0005% per hour Resolution: ±0.0005% Accuracy: ±0.004%	FLUKE Model 332A	PERFORMANCE CHECKING -AC Measurement Check -AC Preliminary Calibration	 4-15 4-29
Transfer Standard	Voltage: 1 to 1000 volts Frequency: 400 Hz, 10 kHz, and 20 kHz Accuracy: 0.01%	FLUKE Model 540B	PERFORMANCE CHECKING -AC Measurement Check -AC Preliminary Calibration	 4-15 4-29
AC Source	Voltage: 1 to 1000 volts Frequency: 400 Hz, 10 kHz, and 20 kHz Stability: 0.01% per hour Distortion: Less than 0.05% for each odd harmonic and 1% for each even harmonic	Optimation Model AC-101	PERFORMANCE CHECKING -AC Measurement Check -AC Preliminary Calibration	 4-15 4-29
Wave Analyzer	Frequency: 1 kHz to 1 MHz	Hewlett Packard Model 310A	PERFORMANCE CHECKING -AC Measurement Check -AC Preliminary Calibration	 4-15 4-29

Figure 4-1. TEST EQUIPMENT REQUIREMENTS (Sheet 2 of 2)

4-11. NULL DETECTOR CHECK

4-12. The null detector is checked in this procedure by using the instruments internal reference supply and Kelvin-Varley divider. This is possible because the reference supply and Kelvin-Varley divider are a few hundred times more accurate than the null detector. If the instrument fails to pass this check, there is a remote chance that the cause is due to a faulty reference supply or Kelvin-Varley divider. In this case, the measurement of an appropriate voltage in the TVM mode will indicate if the null detector is operating properly. Proceed as follows:

a. Set 883A meter to zero with mechanical zero control.
b. Set POWER switch to LINE OPR with 883AB or to ON with 883A and allow a warmup period of 5 minutes.
c. Short INPUT post to COMMON post.
d. Set ac-dc switch to + (positive).
e. Set switches on voltmeter as shown in figure 4-2. Meter should indicate within 1-1/2 small scale divisions (±3% of null range) of value shown in figure 4-2.

VOLTMETER SWITCH SETTINGS			
RANGE	NULL	VOLTAGE READOUT DIALS A B C D E	METER INDICATION
10	1.0	1. 0 0 0 00	-1.0
10	.1	0. 1 0 0 00	-1.0
10	.01	0. 0 1 0 00	-1.0
10	.001	0. 0 0 1 00	-1.0
1	.1	.1 0 0 0 00	-1.0
1	.01	.0 1 0 0 00	-1.0
1	.001	.0 0 1 0 00	-1.0
Before proceeding, set RANGE switch to 1, NULL switch to .0001, all voltage readout to zero, and null meter by adjusting electronic ZERO control.			
1	.0001	0 0 0 1 00	-1.0
100	10	1 0. 0 0 00	-1.0
100	1	0 1. 0 0 00	-1.0
100	.1	0 0. 1 0 00	-1.0
100	.01	0 0. 0 1 00	-1.0
1000	100	1 0 0. 0 00	-1.0
1000	10	0 1 0. 0 00	-1.0
1000	1	0 0 1. 0 00	-1.0
1000	.1	0 0 0. 1 00	-1.0
10	1	0. 1 0 0 00	-0.1
10	1	0. 2 0 0 00	-0.2
10	1	0. 3 0 0 00	-0.3
10	1	0. 4 0 0 00	-0.4
10	1	0. 5 0 0 00	-0.5
10	1	0. 6 0 0 00	-0.6
10	1	0. 7 0 0 00	-0.7
10	1	0. 8 0 0 00	-0.8
10	1	0. 9 0 0 00	-0.9
10	1	1. 0 0 0 00	-1.0
10	1	1. 1 0 0 00	-1.1

Figure 4-2. SETTINGS FOR NULL DETECTOR CHECK

f. Remove short from between INPUT and COMMON posts and set POWER switch to OFF.

4-13. DC DIFFERENTIAL MEASUREMENT CHECK

4-14. The following procedure checks the accuracy of the instrument with full input on each dc range and also with each voltage readout dial set to 1, then to 2, 3, 4, 5, 6, 7, 8, and 9 on the 10 volt range. This method allows the accuracy to be checked with a minimum number of measurements. Proceed as follows:

a. Set meter to zero with mechanical zero control.
b. Set POWER switch to LINE OPR with 883AB or to ON with 883A and allow voltmeter to warmup to equilibrium temperature (about 5 minutes).
c. Set up the necessary equipment to provide dc voltages of 1, 10, 100, and 1000 volts with an accuracy of ±(0.0015% + 2 uv). Proceed as follows:
(1) Connect equipment as shown in figure 4-3.

CAUTION

Make sure HIGH VOLTAGE switch on 412B Power Supply is set to off.



Figure 4-3. DIFFERENTIAL MEASUREMENT CHECK AND CALIBRATION SETUP

(2) Turn on all equipment and allow it to warmup to equilibrium temperature (about 1/2 hour).
(3) Set STANDARD CELL VOLTAGE switches on 750A Reference Divider to voltage of standard cell.

(4) Set INPUT switch on 750A Reference Divider to 1000 volts.

(5) Set voltage dials on 412B Power Supply to 1000 volts.

(6) Set HIGH VOLTAGE switch on 412B Power Supply to ON.

(7) Set 845A Null Detector to 100 MICROVOLTS.

(8) Adjust voltage dials on 412B Power Supply and COARSE and FINE dials on 750A Reference Divider for a null in each successively more sensitive null range on 845A Null Detector. The null detector should be zeroed as necessary.

(9) Voltages of 1, 10, 100, and 1000 volts dc are available at the OUTPUT terminals when the OUTPUT switch is set to the 1, 10, 100, and 1000 volt positions respectively. Note that COARSE and FINE dials on 750A Reference Divider and possibly voltage dials on 412B Power Supply may have to be adjusted to maintain a null on 845A Null Detector due to drifting or loading of the reference divider.

d. Connect 883A ground post to line ground.

e. Short INPUT post to COMMON post.

f. Set 883A ac-dc POLARITY switch to +, RANGE switch to 1, NULL switch to .0001, and all voltage readout dials to 0 (zero).

g. Null meter by adjusting electronic zero control (R239).

h. Remove short from between INPUT and COMMON posts.

i. Set 883A NULL switch to 0.1 and voltage readout dials to 1.000000.

j. Apply 1 volt dc ±(0.0015% + 2 uv) between INPUT and COMMON posts.

k. Adjust voltage readout dials for zero meter deflection in each successively more sensitive null range. Final voltage readout dial setting should be between .999950 and 1.000050.

l. Set 883A RANGE switch to 10, NULL switch to 1, and voltage readout dials to 10.00000.

m. Apply 10 volts dc ±0.0015% between INPUT and COMMON posts.

n. Adjust voltage readout dials for zero meter deflection in each successively more sensitive null range. Final voltage readout dial setting should be between 9.99950 and 10.00050.

o. Set 883A RANGE switch to 100, NULL switch to 10, and voltage readout dials to 100.0000.

p. Apply 100 volts dc ±0.0015% between INPUT and COMMON posts. Note that voltage dials on 412B Power Supply and COARSE and FINE dials on 750A Reference Divider must be readjusted for a null on 845A Null Detector due to loading of voltmeter on 750A Reference Divider.

q. Adjust voltage readout dials for zero meter deflection in each successively more sensitive null range. Final voltage readout dial setting should be between 99.9950 and 100.0050.

r. Set 883A RANGE switch to 1000, NULL switch to 100, and voltage readout dials to 1000.000.

s. Apply 1000 volts dc ±0.0015% between INPUT and COMMON posts. Note that voltage dials on 412B Power Supply and COARSE and FINE dials on 750A Reference Divider must be readjusted for a null on 845A Null Detector because the voltmeter no longer loads 750A Reference Divider.

t. Adjust voltage readout dials for zero meter deflection in each successively more sensitive null range. Final voltage readout dial setting should be between 999.950 and 1000.050.

u. Set up the necessary equipment to provide voltage of 1.111111, 2.222222, ... , 9.999999 volts dc with an accuracy of ±(0.0015% + 2 uv). Proceed as follows:

(1) Set HIGH VOLTAGE switch to off on 412B Power Supply.

(2) Reconnect OUTPUT of 750A Reference Divider to INPUT of 720A Kelvin-Varley Divider as shown in figure 4-4.



Figure 4-4. REFERENCE SUPPLY AND EXTERNAL KELVIN-VARLEY DIVIDER CHECK SETUP

(3) Set voltage dials to 10 volts on 412B Power Supply.

(4) Set INPUT switch and OUTPUT switch on 750A Reference Divider to 10 volts.

(5) Set HIGH VOLTAGE switch to ON on 412B Power Supply.

(6) Set 845A Null Detector to 100 MICROVOLTS.

(7) Adjust voltage dials on 412B Power Supply and COARSE and FINE dials on 750A Reference Divider for a null in each successively more sensitive null range on 845A Null Detector. The null detector should be zeroed as necessary.

(8) Voltages of 1.111111, 2.222222, ... 9.999999 volts dc are available at the OUTPUT terminals of 720A Kelvin-Varley Divider when all voltage dials are set to 1, 2, ... 9 respectively.

v. Set RANGE switch to 10 and NULL switch to .001 on 883A.

w. Apply voltages listed in figure 4-5 between INPUT

and COMMON posts of 883A, set voltage readout dials on 883A as indicated for applied voltage, and adjust voltage readout dials for a null on 883A meter. Final voltage readout dial settings should be within the values listed in figure 4-5.

VOLTAGES APPLIED TO 883A	INITIAL VOLTAGE READOUT DIAL SETTING	FINAL VOLTAGE READOUT DIAL SETTING
1.111111	1.11111	1.11103 to 1.11119
2.222222	2.22222	2.22209 to 2.22236
3.333333	3.33333	3.33314 to 3.33353
4.444444	4.44444	4.44420 to 4.44469
5.555555	5.55555	5.55525 to 5.55586
6.666666	6.66666	6.66631 to 6.66702
7.777777	7.77777	7.77736 to 7.77819
8.888888	8.88888	8.88842 to 8.88936
9.999999	9.99999	9.99947 to 10.00052

Figure 4-5. VOLTAGE READOUT DIAL LIMITS

4-15. AC MEASUREMENT CHECK

4-16. The following procedure checks the accuracy of the instrument with full input on each ac range at 400 Hz and 20 kHz. Proceed as follows:

a. Zero instrument as stated in paragraph 2-7.
b. Set switches on voltmeter as follows:

RANGE	10
NULL	TVM
ac-dc polarity	AC
voltage readout dials	10.00000

c. Set up the necessary equipment to provide 1000, 100, 10, and 1 volts ac rms such that the average value has an accuracy of 0.03% at 400 Hz and 0.1% at 20 kHz including harmonic distortion.

NOTE

Odd harmonic distortion will cause a maximum error equal to the percent distortion divided by the order of the harmonic. For example, third harmonic distortion of 0.03% will cause an error between -0.01% and +0.01% depending on the phase relationship.

Proceed as follows:

(1) Connect all test equipment as shown in figure 4-6.
(2) Turn on all test equipment and allow it to warmup to equilibrium temperature (about 1/2 hour).
(3) Set dc voltage standard to rms value of ac voltage required.
(4) Apply output of dc voltage standard to transfer standard and null galvanometer by adjusting internal reference supply of transfer standard.
(5) Apply output of ac source to transfer standard and null galvanometer by adjusting ac source voltage. The output of the ac source now equals the required voltage.
(6) Check output of ac source with a wave analyzer to make sure that harmonic distortion is not excessive.

d. Complete procedure indicated for each horizontal line of figure 4-7.

4-17. CALIBRATION

4-18. GENERAL

4-19. The 883A should be calibrated as often as deemed necessary. However, it is recommended that DC Differential Voltmeter Calibration be done every 6 months. The AC to DC Converter Calibration should be done



Figure 4-6. AC TO DC CONVERTER CALIBRATION SETUP

Set RANGE switch to	Set NULL switch to	Apply the following voltage between INPUT and COMMON posts	Adjust voltage readout dials for zero meter deflection in each successively more sensitive null range. Final voltage readout dial setting should be between
1	TVM	1 vac, 400 Hz, ±0.03%	.999400 to 1.000600
1	TVM	1 vac, 20 kHz, ±0.10%	.998000 to 1.002000
10	TVM	10 vac, 400 Hz, ±0.03%	9.99400 to 10.00600
10	TVM	10 vac, 20 kHz, ±0.10%	9.98000 to 10.02000
100	TVM	100 vac, 400 Hz, ±0.03%	99.9400 to 100.0600
100	TVM	100 vac, 20 kHz, ±0.10%	99.8000 to 100.2000
1000	TVM	1000 vac, 400 Hz, ±0.03%	999.200 to 1000.800
1000	TVM	1000 vac, 20 kHz, ±0.10%	998.000 to 1002.000

Figure 4-7. AC MEASUREMENT CHECK

every 2 months. For special applications where extreme accuracy is required, it may be desired to calibrate the instrument more frequently. Calibration should be accomplished under typical laboratory conditions in a draft free area with an ambient temperature of 72.5 (±2.5)° F for maximum accuracy. The recommended equipment and the specification required for calibration are shown in figure 4-1. All controls may be located with the aid of figure 4-8.

4-20. DC DIFFERENTIAL VOLTMETER CALIBRATION

4-21. For convenience, DC Differential Voltmeter Calibration is divided into five parts: Preliminary Calibration, Null Detector Calibration, 10 Volt Range Calibration, 1 Volt Range Calibration, and 100 & 1000 Volt Range Calibration. Calibration is normally done by performing all five parts in the sequency given here. However, the calibration procedure is written so that



Figure 4-8. ADJUSTMENT LOCATIONS

any section may be calibrated by performing the calibration procedure for that section after performing DC Preliminary Calibration.

4-22. DC PRELIMINARY CALIBRATION

a. Set meter to zero with mechanical zero control.

b. Set switches on 883A as follows:

RANGE	10
NULL	0.001
ac-dc polarity	+
all voltage readout dials	0 (zero)

c. Set POWER switch to LINE OPR with 883AB or to ON with 883A and allow voltmeter to warmup to equilibrium temperature (about 5 minutes).

d. Set up the necessary equipment to provide dc voltages of 100, 10, and 1 volts with an accuracy of ±(0.0015 % + 2 uv). Proceed as follows:

(1) Connect equipment as shown in figure 4-3.

CAUTION

Make sure HIGH VOLTAGE switch on 412B Power Supply is set to off.

(2) Turn on all equipment and allow it to warmup to equilibrium temperature (about 1/2 hour).

(3) Set STANDARD CELL VOLTAGE switches on 750A Reference Divider to voltage of standard cell.

(4) Set INPUT VOLTAGE switch on 750A Reference Divider to 100 volts.

(5) Set voltage dials on 412B Power Supply to 100 volts.

(6) Set HIGH VOLTAGE switch on 412B Power Supply to ON.

(7) Set 845A Null Detector to 100 MICROVOLTS.

(8) Adjust voltage dials on 412B Power Supply and COARSE and FINE dials on 750A Reference Divider for a null in each successively more sensitive null range on 845A Null Detector. The null detector should be zeroed as necessary.

(9) Voltages of 100, 10, and 1 volts dc are available at the OUTPUT VOLTAGE terminals when the OUTPUT VOLTAGE switch is set to the 100, 10 and 1 volt positions respectively.

e. Connect 883A ground post to line ground.

4-23. NULL DETECTOR CALIBRATION

a. Short INPUT post to COMMON post and null meter by adjusting electronic ZERO control (R239).

b. Set switches on 883A as follows:

RANGE	1
NULL	0.1
voltage readout dial A	1

c. Adjust 1 mv gain control R230 for full scale deflection to the left (-1).

d. Set switches on 883A as follows:

RANGE	1
NULL	0.0001
all voltage readout dials	0 (zero)

e. Null meter by adjusting electronic ZERO control (R239). Right side panel must be on instrument when making this adjustment.

f. Set voltage readout dial D to 1 and adjust 100 uv gain control R231 so that meter indicates full scale (-1) when right side panel is replaced.

g. Remove short from between INPUT and COMMON posts.

4-24. 10 VOLT RANGE CALIBRATION

a. Set switches on 883A as follows:

RANGE	10
NULL	1.0
voltage readout dials	10.00000

b. Apply 10 volts dc (±0.0015%) between INPUT and COMMON posts.

c. Adjust 10 volt range control R119 for a zero meter deflection in each successively more sensitive null range.

4-25. 1 VOLT RANGE CALIBRATION

a. Short INPUT post to COMMON post.

b. Set switches on 883A as follows:

RANGE	1
NULL	0.0001
all voltage readout dials	0 (zero)

c. Null meter by adjusting electronic ZERO control (R239). Right side panel must be on instrument when making this adjustment.

d. Remove short from between INPUT and COMMON posts.

e. Set switches on 883A as follows:

RANGE	1
NULL	0.1
voltage readout dials	1.000000

f. Apply 1 volt dc ±(0.0015% + 2 uv) between INPUT and COMMON posts.

g. Adjust 1 volt range control R121 for zero meter deflection in each successively more sensitive null range. Right side panel must be on instrument when making this adjustment.

4-26. 100 AND 1000 VOLT RANGE CALIBRATION

a. Set switches on 883A as follows:

RANGE	100
NULL	10
voltage readout dials	100.0000

b. Apply 100 volts dc (±0.0015%) between INPUT and COMMON posts.

c. Adjust input attenuator control R103 for zero meter deflection in each successively more sensitive null range. Note that this adjustment calibrates both the 100 and 1000 volt range.

4-27. AC TO DC CONVERTER CALIBRATION

4-28. The dc differential voltmeter section of the voltmeter must be within specifications before the ac to dc converter can be accurately calibrated. The ac to dc converter must be calibrated in the following order.

4-29. AC PRELIMINARY CALIBRATION

a. Zero instrument as stated in paragraph 2-7.
b. Set switches on voltmeter as follows:

RANGE	1
NULL	TVM
ac-dc polarity	AC
voltage readout dials	1.000000

c. Set up the necessary equipment to provide: 100, 10, and 1 volts ac rms such that the average value has an accuracy of 0.03% at 400 Hz and 0.1% at 20 kHz including harmonic distortion; 500 or 1000 volts ac rms such that the average value has an accuracy of 0.03% at 400 Hz and 0.05% at 10 kHz including harmonic distortion.

NOTE

Odd harmonic distortion will cause a maximum error equal to the percent distortion divided by the order of the harmonic. For example, third harmonic distortion of 0.03% will cause an error between -0.01% and +0.01% depending on the phase relationship.

Proceed as follows:

(1) Connect all test equipment as shown in figure 4-6.
(2) Turn on all test equipment and allow it to warmup to equilibrium temperature (about 1/2 hour).
(3) Set dc voltage standard to rms value of ac voltage required.
(4) Apply output of dc voltage standard to transfer standard and null galvanometer by adjusting internal reference supply of transfer standard.
(5) Apply output of ac source to transfer standard and null galvanometer by adjusting ac source voltage. The output of the ac source now equals the required voltage.
(6) Check output of ac source with a wave analyzer to make sure that harmonic distortion is not excessive.

4-30. 1 VAC CONVERTER GAIN ADJUSTMENT

a. Apply 1 volt ac (±0.03%) at 400 Hz between INPUT and COMMON posts.
b. Set NULL switch to .001.
c. Adjust 1 vac gain adjust control R503 until meter needle is within 100 microvolts (1 major division) of null.

4-31. 1 VAC HIGH FREQUENCY ADJUSTMENT

a. Apply 1 volt ac (±0.1%) at 20 kHz between INPUT and COMMON posts.

NOTE

The capacitors used for converter frequency adjustments in current instruments have improved humidity protection over the older type. For these instruments a small cap must be unscrewed and removed before making any adjustments and then it must be replaced. These improved capacitors for C401, C403, and C405 are used in serial numbers 570 and on, and for C502 in serial numbers 590 and on.

b. Adjust 1 vac high frequency trim control C502 until meter needle is within 100 microvolts (1 major division) of null.

4-32. 10 VAC ATTENUATOR ADJUSTMENT

a. Set RANGE switch to 10 and NULL switch to TVM.
b. Apply 10 volts ac (±0.03%) at 400 Hz between INPUT and COMMON posts.
c. Set NULL switch to .01.
d. Adjust 10 vac attenuator control R403 until meter needle is within 0 to +1 millivolt (0 to +1 major division) of null. Note that 10, 100, and 1000 volt attenuator controls and 10, 100, and 1000 volt high frequency controls are located from left to right respectively on bracket next to converter board.

4-33. 10 VAC HIGH FREQUENCY ADJUSTMENT

a. Apply 10 volts ac (±0.1%) at 20 kHz between INPUT and COMMON posts.
b. Adjust 10 vac high frequency trim control C401 until meter needle is within 1 millivolt (1 major division) of null.

4-34. 100 VAC ATTENUATOR ADJUSTMENT

a. Set RANGE switch to 100 and NULL switch to TVM.
b. Apply 100 volts ac (±0.03%) at 400 Hz between INPUT and COMMON posts.
c. Set NULL switch to .1.
d. Adjust 100 vac attenuator control R406 until meter needle is within 0 to +10 millivolts (0 to +1 major division) of null.

4-35. 100 VAC HIGH FREQUENCY ADJUSTMENT

a. Apply 100 vac (±0.1%) at 20 kHz between INPUT and COMMON posts.
b. Adjust 100 vac high frequency trim control C403 until meter needle is within 10 millivolts (1 major division) of null.

4-36. 1000 VAC ATTENUATOR ADJUSTMENT

a. Set RANGE switch to 1000, NULL switch to 1, and voltage readout dials to 500.000.
b. Apply 500 volts ac (±0.03%) at 400 Hz between INPUT and COMMON posts.
c. Adjust 1000 vac attenuator control R410 until meter needle is within 50 millivolts (1/2 major division) of null.

NOTE

The preferable calibration voltage for this adjustment is 500 volts ac. If 500 volts ac is not available, 1000 volts ac may be used

by adjusting R410 until meter needle is within 100 millivolts (1 major division) of null.

4-37. 1000 VAC HIGH FREQUENCY ADJUSTMENT

a. Apply 500 volts ac (±0.05%) at 10 kHz between INPUT and COMMON posts.

b. Adjust 1000 vac high frequency trim control C405 until meter needle is within 50 millivolts (1/2 major division) of null.

NOTE

The preferable calibration voltage for this adjustment is 500 volts ac. If 500 volts ac is not available, 1000 volts ac may be used by adjusting C405 until meter needle is within 100 millivolts (1 major division) of null.

4-38. CORRECTIVE MAINTENANCE

4-39. GENERAL

4-40. Since the 883A AC/DC Differential Voltmeter is a completely transistorized instrument of conservative design, the possibility of a component failure is greatly reduced. Under normal circumstances, the only thing that will interfere with the operation of the instrument is the need for calibration. However, if the instrument does not perform correctly after calibration, the technician may use the information given here as a complete guide for locating and correcting the source of trouble. All equipment required for maintaining the instrument is listed in figure 4-1.

4-41. TROUBLESHOOTING

4-42. TROUBLESHOOTING TIPS. The purpose of troubleshooting is to quickly and accurately correct the cause of any abnormal condition. Thus, servicing should begin with an attempt to localize the general area of trouble. By performing a complete performance check as outlined in paragraph 4-8, the trouble may be isolated to the null detector, reference supply, Kelvin-Varley divider, dc input attenuator, or ac to dc converter. To assist in localizing some of the more common troubles that might occur, the causes and remedies for a number of symptoms are listed in the troubleshooting chart (figure 4-9). However, an understanding of the theory of operation and frequent reference to the schematic diagram is the best way to locate the cause of any abnormal condition.

4-43. VISUAL INSPECTION. Trouble can sometimes be found by a thorough visual inspection. Look for:

a. Accumulations of dirt, dust, moisture, or grease. Remove contamination as outlined in periodic maintenance (paragraph 4-5).

b. Scorched or burned parts. Damage of this type is often due to some other defective component. Determine cause of damage before replacing overheated part.

CAUTION

Avoid touching polyethelene grommets. The grease on the hands of some people can cause excessive electrical leakage.

c. Cracks, cuts, and other damage to polyethelene grommets. Replace grommets using a plastic bag over the hand to prevent contamination.

d. Input divider resistors (R100, R101, and R102) touching printed circuit board. When these resistors touch the board, leakage paths are created which can result in meter offset.

e. Loose or intermittent connections.

f. Any other condition which suggests a source of trouble.

4-44. VOLTAGE LEVEL CHECKING. When the trouble has been localized to a stage, the defective part may be isolated by voltage level measurements at the transistor terminals. Figure 4-10 may be used to locate the transistor terminals. When making measurements on printed circuit boards, use a sharp probe and press firmly while rotating probe to break through the insulating

SYMPTOM	PROBABLE CAUSE	REMEDY
Drift of reference supply evidenced by null detector meter needle drift when measuring an extremely stable voltage.	A wire wound resistor (R108, R109, R115, R116, R118, R120, or R122) changing value with temperature.	Locate faulty resistor by heating slightly with a soldering iron held near resistor, while looking for a meter needle change of a standard cell measurement.
	Battery Voltage Low.	Charge Batteries
	Faulty Zener diode.	Monitor voltage across Zener diode pair. Look for drift of Zener voltage. Replace if defective.
	Q101, Q102, Q103, Q104, or Q105 defective.	Check by replacement.

Figure 4-9. TROUBLESHOOTING CHART (Sheet 1 of 2)

SYMPTOM	PROBABLE CAUSE	REMEDY
Meter rattle or drift.	Field effect transistor Q201 defective.	Check as outlined in paragraph 4-46. If rattle is excessive, check Q201 by replacement.
	Chopper G201 defective.	Check as outlined in paragraph 4-46. If rattle is excessive, check G201 by replacement.
	Moisture, dirt, or other contamination on printed circuit boards or switches.	Clean instrument as outlined in paragraph 4-5.
Measurements are out of tolerance on every range when Kelvin-Varley divider is dialed to any setting other than 10999100.	Out of adjustment or one of the Kelvin-Varley divider resistors is out of tolerance.	Check accuracy of Kelvin-Varley divider using paragraph 4-51. If these checks indicate an out of tolerance condition, first try adjusting Kelvin-Varley divider using procedure of paragraph 4-60. If Kelvin-Varley divider cannot be adjusted, use out of tolerance data obtained from procedure of paragraph 4-51 to isolated defective resistor.
Meter cannot be brought to zero with ZERO control.	Chopper drive not symmetrical.	Readjust chopper drive circuit using procedure of paragraph 4-55.
	CR201 or CR202 defective.	Check and replace if defective.
Meter beating with voltage under measurement.	Chopper drive circuit out of adjustment.	Adjust chopper drive circuit using procedure of paragraph 4-55.
NOTE: Assuming all dc measurements are normal, the following symptoms are common to ac measurements only.		
Measurements are out of tolerance on the 1000, 100, or 10 volt ac range only.	Out of calibration.	Recalibrate per paragraph 4-27.
	One or more resistors in the 1000, 100, or 10 volt ac attenuator has shifted in value.	Recalibrate per paragraph 4-27.
Measurements are out of tolerance on all ac ranges.	Out of calibration.	Recalibrate per paragraph 4-27.
	Transistor Q501, Q502, Q503, Q504, Q505, or Q506 faulty.	Check by measuring dc bias voltages or by replacement.
	R501, R504, R530, or R531 has shifted in value.	Recalibrate per paragraph 4-27.
Measurements are out of tolerance at some frequencies.	Out of calibration.	Recalibrate per paragraph 4-27.
	Faulty frequency compensation capacitor.	Locate faulty capacitor and replace. If trouble occurs on all ranges, check C501 and C503. If trouble occurs on 1000 volt range only, check C406 and C407. If trouble occurs on 100 volt range only check C404. If trouble occurs on 10 volt range only, check C402.

Figure 4-9. TROUBLESHOOTING CHART (Sheet 2 of 2)



Figure 4-10. TRANSISTOR TERMINAL LOCATIONS

coating. Measurements that differ widely from those listed in the transistor voltage chart (figure 4-11) can be used along with the schematic to localize the trouble to a specific part, in most cases.

CAUTION

When measuring voltage, it is recommended that care be used to avoid momentary short circuits which could damage components.

4-45. TROUBLESHOOTING CHECKS. The following troubleshooting checks list several normal conditions that should exist in the instrument. The most probable cause or causes of an abnormal condition in these checks is also given.

4-46. Meter Rattle Check. If the meter needle appears to rattle excessively, perform the following check:

a. Set switches on 883A as follows:

TRANSISTOR	EMITTER	BASE	COLLECTOR
Q101	-30 (1)	-29.4	-18.0 (2)
Q102	-13	-12.4	- 7.1
Q103	-13	-12.4	- 6.7
Q104	- 6.5	- 7.1	-29.4
Q105	- 6.5	- 6.7	-18.0 (2)
Q106	6.9 (5)	5.9	3.0
Q107	6.9 (5)	5.9	3.0
Q108	0	.16	3.0
Q109	0	.16	3.0
Q201	- 3.3 (SOURCE)	0 (GATE)	-10 (DRAIN)
Q202	-16.6	-16	-12.4
Q203	-13	-12.4	-10
Q204	-18.0 (2)	-17.4	-15.4
Q205	-16	-15.4	- 9.5
Q206	0	+ 2.5	0
Q501	7.1 (SOURCE)	5.5 (GATE)	11 (DRAIN)
Q502	0	0.6	3.5
Q503	2.7	3.5	8.2
Q504	0	0.7	3.7
Q505	11.3	11.9	18.0 (4)
Q506	3.0	3.7	9.5
Q507	34.0 (3)	33	18.0 (4)
Q508	1.7	2.2	33
Q509	6.8	6.2	2.2

The above operating voltage levels are measured under the following conditions: (a) Line voltage at 115/230 vac, 50 to 440 Hz. (b) All voltages measured with a 3%, 10 megohm, 5 pf voltmeter unless otherwise indicated. (c) All voltages for Q501 to Q509 are measured from specified terminal to ac to dc converter common. The COMMON post is ac to dc converter common when ac-dc polarity switch is set to AC. (d) All other voltages are measured from specified terminal to reference supply - null detector common. The COMMON post is reference supply - null detector common when in TVM mode or when in a NULL mode with all voltage dials set to 0 and polarity switch set to +. (e) Some voltages may vary as much as 15 to 20%; (f) Bias voltages (difference between emitter and base voltages) should remain approximately the same; (g) All voltages are dc unless otherwise indicated.

NOTES: (1) Emitter of Q101 as measured with a differential voltmeter should be between -26 and -34 vdc for ON (883A) and LINE OPR (883AB) at 115/230 vac line, -19.5 and -21.0 vdc for BAT OPR (883AB only), and not less than -23.5 vdc for BAT CHG (883AB only) at 115/230 vac line. (2) Collector of Q101 and Q105 and emitter of Q204 as measured with a differential voltmeter should be between -17.9 and -18.1 vdc. (3) Emitter of Q507 as measured with a differential voltmeter should be between +26 and +35 vdc for ON (883A) and LINE OPR (883AB) at 115/230 vac line, +19.5 and +21.0 vdc for BAT OPR (883AB only), and not less than +23.5 vdc for BAT CHG (883AB only) at 115/230 vac line. (4) Collector of Q507 and Q505 as measured with a differential voltmeter should be between +17.9 and +18.1 vdc with less than 200 uv ripple. (5) Emitter of Q106 and Q107 as measured with a differential voltmeter should be between +6.3 and +7.0 vdc for ON (883A) and LINE OPR (883AB) at 115/230 vac line and +4.9 and +5.3 vdc for BAT OPR (883AB only).

Figure 4-11. TRANSISTOR VOLTAGE CHART

RANGE	1
NULL	.0001
ac-dc polarity	+
all voltage readout dials	0 (zero)

b. Set POWER switch to LINE OPR with 883AB or to ON with 883A and allow a 5 minute warmup period.
c. Short INPUT post to COMMON post. Random excursions of meter needle should be less than 1 small division peak-to-peak. If rattle is excessive, check field-effect transistor Q201 by replacement. If meter rattle is still excessive, chopper is probably faulty.

4-47. Leakage Resistance Check. Leakage from the -18 volt supply to chassis ground causes an error in differential measurements. This error is much greater in the negative polarity because the leakage current flows through the tvm attenuator in the negative polarity. This provides a convenient way to check for excessive leakage. Proceed as follows:

a. Zero instrument as stated in paragraph 2-7.
b. Short COMMON post to chassis ground post.
c. Set switches on instrument as follows:

RANGE	1
NULL	.0001
ac-dc polarity	- (negative)
all voltage readout dials	0 (zero)

d. Meter needle should indicate less than 1/2 major division (5 uv). If leakage is excessive, clean instrument as instructed in paragraph 4-5 and check polyethelene grommets as instructed in paragraph 4-43.

4-48. Reference Voltage Regulation Check. If the reference voltage is suspected of being faulty, perform the following check:

a. Connect adjustable autotransformer to line power.
b. Connect 883A line cord to output of autotransformer.
c. Set POWER switch to LINE OPR with 883AB or to ON with 883A and allow a 5 minute warmup period.
d. Set autotransformer to 103 volts (207 volts when 883A is wired for 230 volts nominal) as measured with a VTVM.
e. Set NULL switch to TVM and ac-dc polarity switch to +.
f. Differentially measure -18 volt supply between COMMON post and collector of Q101 with a differential voltmeter.
g. Set autotransformer to 127 volts (253 volts when 883A is wired for 230 volts nominal) as measured with a VTVM. Output of -18 volt supply should change by less than 3.5 millivolts from step f. If regulation is excessive, check transistors Q101 through Q105.

4-49. Common Model Measurement Check. If the instrument is suspected of making incorrect common mode measurements, perform the following check:

a. Measure the voltage of a standard cell in the 1 volt range and in the positive polarity.
b. Connect 500 volts dc from chassis ground post to COMMON post and wait about 3 minutes.
c. Measure voltage of standard cell. If the measurements are not within 50 microvolts of each other, there is excessive electrical leakage to ground. Clean instrument as instructed in paragraph 4-5.

4-50. Converter Offset Check. If low level voltage measurements are not accurate, perform the following check:

a. Set switches on 883A as follows:

RANGE	1
NULL	.001
ac-dc polarity	AC
all voltage readout dials	0 (zero)

b. Set POWER switch to LINE OPR with 883AB or to ON with 883A and allow a 5 minute warmup period.
c. Short INPUT post to COMMON post. Meter needle should indicate less than 160 uv after all transients have stopped. If noise is excessive, check Q501, CR502, and for converter power supply ripple less than 200 uv.

4-51. Kelvin-Varley Divider Check. The Kelvin-Varley check requires that connections to the Kelvin-Varley divider be made inside the instrument. Also, the Kelvin-Varley check takes a considerable amount of time to perform. Therefore, this check should be performed only if the differential measurement check (paragraph 4-13) indicates there is a problem or if the Kelvin-Varley divider has been adjusted (paragraph 4-60). Proceed as follows:

a. Disconnect 883A from line power.
b. Set POWER switch to OFF and set NULL switch to TVM.
c. Remove bottom panel and top-back panel.
d. Locate high input (wire from Kelvin-Varley board to range switch S2, usually purple or point 13 on Kelvin-Varley board), high output (wire from R12 to null switch S3, usually yellow), and input-output common (wire from Kelvin-Varley board to voltage dial A, S5, usually black or point 1 on Kelvin-Varley board) of Kelvin-Varley divider.

CAUTION

Make sure HIGH VOLTAGE switch on 412B Power Supply is set to off.

e. Connect equipment as shown in figure 4-12.
f. Turn all equipment on and allow it to warmup to equilibrium temperature (about 1/2 hour).
g. Set voltage dials on 412B Power Supply for an output of 11.0 volts dc.
h. Set 883A voltage readout dials to 000000 and 720A Kelvin-Varley Divider dials to 0000000.
i. Set 845A Null Detector to 30 MICROVOLTS.
j. Set function switch to VOLTAGE OFF on 721A Lead Compensator.
k. Zero 845A Null Detector
l. Set function switch to $R_S > R_X$ on 721A Lead Compensator.
m. Adjust LOW BALANCE controls on 721A for a null on 845A. It may be necessary to temporarily reduce sensitivity of 845A to find null point on LOW BALANCE controls.



Figure 4-12. KELVIN-VARLEY DIVIDER CHECK SETUP

n. Set 883A voltage dials to 10999100 and 720A Kelvin-Varley dials to 109999910.

o. Set function switch to VOLTAGE OFF on 721A Lead Compensator.

p. Zero 845A Null Detector.

q. Set function switch to $R_S > R_X$ on 721A Lead Compensator.

r. Adjust HIGH BALANCE controls on 721A for a null on 845A. It may be necessary to temporarily reduce sensitivity of 845A to find null point on HIGH BALANCE controls.

s. Set 845A Null Detector to 300 MICROVOLTS and change to 100 MICROVOLTS and 30 MICROVOLTS as required.

t. Set 883A voltage readout dials and 720A Kelvin-Varley Divider dials to first positions shown in figure 4-13.

u. Set function switch to VOLTAGE OFF on 721A Lead Compensator.

v. Zero 845A Null Detector.

w. Set function switch to $R_S > R_X$ on 721A Lead Compensator. The 845A Null Detector indication should be equal to or less than the listed deviation.

x. Repeat steps u through w for remaining switch positions shown in figure 4-13. If Kelvin-Varley divider is out of tolerance between settings of 1000000 and 0999100, readjust as set forth in paragraph 4-60. If a resistor-trimmer combination of the first deck can not be adjusted for a null during adjustment, the 4999.2 ohm resistor is defective and must be replaced. If Kelvin-Varley divider is out of tolerance for remaining settings, make sure padding trimmers are adjusted correctly (paragraph 4-60) before attempting to replace a resistor.

4-52. ELECTRONIC ADJUSTMENTS

4-53. The following electronic adjustments are not performed during calibration because they may never require adjusting during the life of the instrument under normal circumstances. All controls may be located with the aid of figure 4-8.

4-54. NEGATIVE 18 VOLT SUPPLY ADJUSTMENT. Sampling string resistor R110 should be adjusted whenever a part in the -18 volt power supply is replaced. If R110 is adjusted, it will be necessary to perform the 10 volt and 1 volt range calibration (paragraph 4-24 and 4-25). Proceed as follows:

a. Set POWER switch to LINE OPR with 883AB or to ON with 883A.
b. Set NULL switch to TVM.
c. Connect a differential voltmeter between COMMON post and junction of C104 and R112.
d. Set up differential voltmeter to differentially measure -18.0 volts dc.
e. Adjust R110 for -18.0 (±0.1) volts.
f. Perform 10 volt and 1 volt range calibration.

4-55. CHOPPER DRIVE CIRCUIT ADJUSTMENT. The chopper drive circuit should be adjusted for symmetry and frequency if a part in the chopper drive circuit is replaced, if there is difficulty in zeroing the meter, or if line operation causes the meter to beat due to the relationship of the chopper frequency with the line power frequency. Proceed as follows:

a. Set POWER switch to LINE OPR with 883AB or to ON with 883A.
b. Set NULL switch to TVM and ac-dc polarity switch to +.
c. Connect oscilloscope between COMMON post and one side of the chopper drive coil G201 to observe the output waveform.
d. Adjust R125 until output is within ±10% of symmetry.
e. Adjust R123 for a frequency of 84 (±1) Hz.

4-56. NULL DETECTOR INPUT STAGE BIAS ADJUSTMENT. The bias of field-effect transistor Q201 should be adjusted if it or any component in its drain-sink circuit is replaced. Proceed as follows:

a. Set POWER switch to LINE OPR with 881AB or to ON with 883A.
b. Set NULL switch to TVM and ac-dc polarity switch to +.
c. Adjust R208 until voltage from COMMON post to drain of Q201 (junction of C207 and R207) is -10 (±0.5) volts as measured with a VTVM.

4-57. CONVERTER SUPPLY ADJUSTMENT. Sampling string resistor R539 should be adjusted whenever a part in the converter power supply is replaced. Proceed as follows:

a. Set POWER switch to LINE OPR with 883AB or to ON with 883A.
b. Connect a differential voltmeter across C523.
c. Set up differential voltmeter to differentially measure +18.0 vdc.

883A Voltage Dial Settings	Standard Divider Settings	Maximum Deviation for an Input of 11.0 vdc (± microvolts)
1000000	10000000	200
9999100	10000000	200
900000	9000000	180
8999100	9000000	180
800000	8000000	160
7999100	8000000	160
700000	7000000	140
6999100	7000000	140
600000	6000000	120
5999100	6000000	120
500000	5000000	100
4999100	5000000	100
400000	4000000	80
3999100	4000000	80
300000	3000000	60
2999100	3000000	60
200000	2000000	40
1999100	2000000	40
100000	1000000	20
0999100	1000000	20
090000	0900000	20
0899100	0900000	20
080000	0800000	20
0799100	0800000	20
070000	0700000	20
0699100	0700000	20
060000	0600000	20
0599100	0600000	20
050000	0500000	20
0499100	0500000	20
040000	0400000	20
0399100	0400000	20
030000	0300000	20
0299100	0300000	20
020000	0200000	20
0199100	0200000	20
010000	0100000	20
0099100	0100000	20
009000	0090000	20
0089100	0090000	20
008000	0080000	20
0079100	0080000	20

883A Voltage Dial Settings	Standard Divider Settings	Maximum Deviation for an Input of 11.0 vdc (± microvolts)
007000	0070000	20
0069100	0070000	20
006000	0060000	20
0059100	0060000	20
005000	0050000	20
0049100	0050000	20
004000	0040000	20
0039100	0040000	20
003000	0030000	20
0029100	0030000	20
002000	0020000	20
0019100	0020000	20
001000	0010000	20
0009100	0010000	20
000900	0009000	20
0008100	0009000	20
000800	0008000	20
0007100	0008000	20
000700	0007000	20
0006100	0007000	20
000600	0006000	20
0005100	0006000	20
000500	0005000	20
0004100	0005000	20
000400	0004000	20
0003100	0004000	20
000300	0003000	20
0002100	0003000	20
000200	0002000	20
0001100	0002000	20
000100	0001000	20
0000100	0001000	20
000090	0000900	20
000080	0000800	20
000070	0000700	20
000060	0000600	20
000050	0000500	20
000040	0000400	20
000030	0000300	20
000020	0000200	20
000010	0000100	20
000000	0000000	0

Figure 4-13. KELVIN-VARLEY DIVIDER ERROR LIMITS

d. Adjust R539 for +18.0 (±0.1) vdc.

4-58. CONVERTER INPUT STAGE BIAS ADJUSTMENT. The bias of field-effect transistor Q501 should be adjusted if it or any component in its drain-sink circuit is replaced. Proceed as follows:

a. Set POWER switch to LINE OPR with 883AB or to ON with 883A.

b. Adjust R508 until voltage from converter common to drain of Q501 (lead from Q501 to R505) is +11.0 (±0.5) vdc as measured with a VTVM.

4-59. CONVERTER OUTPUT ADJUSTMENT. The converter output should be adjusted with R522 when Q505, Q506, or any component in these two stages is replaced. Proceed as follows:

a. Set POWER switch to LINE OPR with 883AB or to ON with 883A.

b. Adjust R522 until voltage from converter common to collector of Q506 is 9.5 (+0.5/-1.5) vdc as measured with a VTVM. If voltage will not reach 9.5 vdc, it should be at least 8.0 vdc.

4-60. KELVIN-VARLEY DIVIDER ADJUSTMENT. The Kelvin-Varley divider should be adjusted only after a resistor has been replaced or after the Kelvin-Varley divider check (paragraph 4-51) indicates that the Kelvin-Varley divider is out of tolerance. Proceed as follows:

a. Disconnect 883A from power line.
b. Set POWER switch to OFF and NULL switch to TVM.
c. Remove bottom cover.
d. Open jumpers marked with a U, V, W, X, Y, and Z by unsoldering one end and pulling it loose. Also unsolder high input of Kelvin-Varley divider (wire from Kelvin-Varley board to range switch S2, usually purple).
e. Connect equipment as shown in figure 4-14.
f. Turn on all equipment and allow it to warmup to equilibrium temperature (about 1/2 hour).

CAUTION

Do not allow power supply voltage to exceed 10 volts as damage to the Kelvin-Varley resistors may result.



Figure 4-14. KELVIN-VARLEY DIVIDER ADJUSTMENT SETUP

g. Set 412B Power Supply for an output of 4 volts dc.
h. Connect points A and C of figure 4-12 to test points 14 and 16 of Kelvin-Varley board respectively.
i. Eliminate errors due to resistance of leads and connections as follows:
(1) Set 845A Null Detector to 30 MICROVOLTS.
(2) Set 720A Kelvin-Varley Divider dials to 0000000.
(3) Connect point B of figure 4-14 to test point that point C is connected to.
(4) Set function switch to VOLTAGE OFF on 721A Lead Compensator.
(5) Adjust ZERO control to null meter on 845A Null Detector.
(6) Set function switch to $R_S > R_X$ on 721A Lead Compensator.
(7) Adjust LOW BALANCE controls on 721A Lead Compensator for a null on 845A. It may be necessary to temporarily reduce sensitivity of 845A to find null point on LOW BALANCE controls.
(8) Set 721A Kelvin-Varley Divider dials to 10000000.
(9) Connect point B of figure 4-14 to test point that point A is connected to.
(10) Repeat steps (4), (5), and (6).
(11) Adjust HIGH BALANCE controls on 721A for a null on 845A. It may be necessary to temporarily reduce sensitivity of 845A to find null point on HIGH BALANCE controls.
j. Set voltage dial E to 50.
k. Connect point B of figure 4-14 to test point 15.
l. Set 720A Kelvin-Varley Divider to 5000000.
m. Eliminate error due to thermal voltages as follows:
(1) Set function switch to VOLTAGE OFF on 721A Lead Compensator.
(2) Set 845A Null Detector to 30 MICROVOLTS and adjust ZERO control to null meter.
(3) Set function switch to $R_S > R_X$ on 721A Lead Compensator.
n. Set 845A Null Detector to 1 MILLIVOLT.
o. Adjust R303 (at point P) to within ±200 microvolts of null.
p. Reconnect points A and C to test points 17 and 18 respectively.
q. Solder down jumpers Z and Y.
r. Repeat step i.
s. Connect point B to test point 19.
t. Repeat steps m and n.
u. Adjust R316 (at point N) to within ±50 microvolts of null.
v. Reconnect points A and C to test points 20 and 21 respectively.
w. Solder down jumpers X and W.
x. Repeat step i.
y. Connect point B to test point 22.
z. Repeat steps m and n.
aa. Adjust R329 (at point M) to within ±20 microvolts of null.
ab. Set 412B Power Supply for an output of 18 volts dc.
ac. Reconnect points A and C to test points 23 and 24 respectively.
ad. Solder down jumper V.
ae. Repeat step i.
af. Connect point B to test point 25.
ag. Set 720A Kelvin-Varley Divider dials to 6666667.
ah. Make adjustments as given in each horizontal line of figure 4-15.
ai. Solder down jumper U and high input wire of Kelvin-Varley divider.
aj. Check accuracy of Kelvin-Varley divider using procedure of paragraph 4-51.

4-61. MECHANICAL DRUM ADJUSTMENTS

4-62. Occasionally the need may arise to align the po-

Set Voltage Dial A To	Short Test Points	Eliminate Thermal Voltage Errors as in step m	Set 845A Null Detector to 100 microvolts	Adjust Control to Within ±15 microvolts of Null at Point		Remove Short from Between
0	2 to 3	"	"	R364	A	2 and 3
0	1 to 2	"	"	R362	B	1 and 2
2	4 to 5	"	"	R360	C	4 and 5
2	3 to 4	"	"	R358	D	3 and 4
4	6 to 7	"	"	R356	E	6 and 7
4	5 to 6	"	"	R354	F	5 and 6
6	8 to 9	"	"	R352	G	8 and 9
6	7 to 8	"	"	R350	H	7 and 8
8	10 to 11	"	"	R348	I	10 and 11
8	9 to 10	"	"	R346	J	9 and 10
10	12 to 13	"	"	R344	K	12 and 13
10	11 to 12	"	"	R342	L	11 and 12

Figure 4-15. KELVIN-VARLEY "A" DECK ADJUSTMENT

larity switch drum or one of the voltage dial drums in the readout windows. Also, if the drive gear on a switch or dial shaft is no longer in line with the drum shaft, the gears may bind as the dials are turned. Proceed as follows:

a. Remove both side front-covers and the bottom cover from 883A.
b. Stand instrument on rear.
c. Make sure that drive gear on polarity switch shaft and drive gear on shaft of voltage dial E are in line with drum shaft. If not, loosen set screw of drive gear with a 1/16" hex key and align drive gear with drum shaft.
d. Loosen adjusting bracket at left side of instrument and position drum shaft up or down until there is just discernible backlash. That is, until polarity drum just moves when rotated with a finger without moving drive gear on polarity switch shaft.
e. Loosen adjusting bracket at right side of instrument and position drum shaft until there is just discernible backlash for drum of voltage dial E.
f. Turn polarity switch and all voltage dials fully counterclockwise.
g. Loosen set screw of drive gear for drum being aligned and slide drive gear toward back of instrument.

NOTE

See step 1. for adjustment of voltage dial E.

h. Insert finger through window and hold drum being aligned in desired position.
i. Insert hex key into set screw of drive gear and lift drive gear into place allowing it to turn counterclockwise as the teeth mesh.
j. When drive gear is in line with drum shaft tighten set screw.
k. Check character alignment in window. If necessary, loosen set screw and rotate drive gear slightly for final adjustment.
l. To align drum for voltage dial E, loosen set screw of drive gear and slide toward rear of instrument.
m. Insert hex key into set screw of drive gear and lift drive gear into alignment with drive shaft while noting how much drum turns.
n. Slide drive gear toward rear of instrument.
o. Position drum so that 00 position will line up with pointer when gear is raised into position.
p. Raise drive gear into alignment with drum shaft and position 00 in line with pointer by rotating drive gear slightly before tightening set screw.

SECTION V

LIST OF REPLACEABLE PARTS

5-1. INTRODUCTION

5-2. This section contains information necessary to describe all normally replaceable parts. Separate assembly lists are used to describe the parts on the final assembly and various assemblies and subassemblies. Each list has a corresponding illustration on which the parts for that list are identified. Parts are called out on both lists and illustrations by reference designations from the schematic diagram. Those parts (mechanical) which have no reference designation are shown on the illustrations by Fluke stock number.

5-3. Each list provides the following information on each part:

a. The REF DESIG. column indicates the reference designation used on the schematic diagram.

b. The DESCRIPTION column describes the part in words, along with any applicable values, tolerances, etc. Indentation is used to show assembly, subassembly, and parts relationship. See abbreviations and symbols on next page.

c. Entries in the FLUKE STOCK NO. column indicate the number by which Fluke stocks the part. This number should be used when ordering parts from the Fluke factory or your Fluke representative.

d. Entries in the MFR. column indicate a typical manufacture of the part by the manufacturer's code number. Appendix A lists the manufacturers and their code numbers.

e. Entries in the MFR. PART NO. column are part numbers assigned by the manufacturer indicated in the Mfg. column.

f. The number in the TOT. QTY. column indicates the total quantity of the part used in the instrument. "REF" indicates that the total quantity of the part has been previously given. The total quantity of each part is listed the first time the part appears. All other listings of the same part refer back to the reference designation of the first appearance of the part for the total quantity.

g. The number in the REC. QTY. column indicates the recommended spares quantity necessary to support approximately one to five instruments for a period of two years. The basis used to select the recommended spares quantity is that a small group of parts will be required to correct a majority of the problems that occur. Since there is a chance that any part may fail, a stock of at least one of every part used in addition to the recommended parts will be needed for complete maintenance during one year of isolated service.

h. The USE CODE column identifies certain parts which have been added, deleted, or modified during production of the instrument. Each part for which a use code has been assigned may be identified with a particular instrument serial number by consulting the Use Code Effectivity List at the end of this section. These changes are normally made when improved components become available or when the latest circuit improvements are developed by our engineering department. The serial number listed indicates the instruments in which that particular part was used. The symbol "~" is used to indicate an approximate use code. If a different part should be used for replacement, it is listed by Fluke stock number in the description column.

5-4. HOW TO OBTAIN PARTS

5-5. Standard components have been used whenever possible. Thus, most parts can be obtained locally. However, parts may be ordered directly from the manufacturer using the manufacturer's part number or from Fluke using the Fluke stock number. In addition, the most commonly replaced parts that can not be obtained locally may be obtained from your Fluke representative. If a part you have ordered has been replaced by a new or improved part, Fluke will normally send you this part along with an explanation.

5-6. When ordering parts from Fluke always include:

a. Reference designation, description, and Fluke stock number.

b. Instrument model and serial number.

c. Most structural parts are not listed. In this case, give complete description, function, and location of part.

5-7. ABBREVIATIONS AND SYMBOLS

ABBREVIATIONS

ac	alternating current	mw	milliwatt
Al	aluminum	na	nanoampere
assy	assembly	pf	picofarad
cap	capacitor	piv	peak inverse voltage
car flm	carbon film	plstc	plastic
cer	ceramic	pp	peak-to-peak
comp	composition	ppm	parts per million
conn	connector	rect	rectifier
cps	cycles per second	res	resistor
db	decibel	rms	root-mean-square
dc	direct current	sb	slow-blow
dpdt	double pole double throw	Si	silicon
dpst	double pole single throw	S/N	serial number
elect	electrolytic	sw	switch
fxd	fixed	spdt	single pole double throw
Ge	germanium	spst	single pole single throw
gmv	guaranteed minimum value	Ta	tantalum
Hz	hertz (cycles per second)	tc	temperature coefficient
K	kilohm	tstr	transistor
kc or Kc	kilocycle	ua	microampere
kHz or KHz	kilohertz (kilocycles per sec)	uf	microfarad
kv	kilovolt	uv	microvolt
kva	kilovolt-ampere	va	volt ampere
ma	milliampere	vac	alternating current volts
Mc or MC	megacycle	var	variable
MHz	megahertz (megacycles per sec)	vdc	direct current volts
meg or M	megohm	w	watt
met flm	metal film	wvdc	direct current working volts
mfg	manufacturer	ww	wirewound
mv	millivolt		

PREFIX SYMBOLS

T	tera	10^{12}
G	giga	10^{9}
M	mega	10^{6}
K or k	kilo	10^{3}
h	hecto	10^{2}
da	deka	10
d	deci	10^{-1}
c	centi	10^{-2}
m	milli	10^{-3}
u	micro	10^{-6}
n	nano	10^{-9}
p	pico	10^{-12}
f	femto	10^{-15}
a	anto	10^{-18}

QUANTITY SYMBOLS

a or amp	ampere
f	farad
h	henry
hr	hour
Ω	ohm
sec	second
v or V	volt
w or W	watt

SPECIAL NOTES AND SYMBOLS

~	Approximate use code, or serial number.	Use 0000-000000	Part number indicated should be used if replacement is required.

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	Final Assembly (line powered model) (battery-line powered model)	883A 883AB			-		
	Front Panel Assembly (see Figure 5-2)	3158-166066	89536	3158-166066	1		
		3158-166157	89536	3153-166157	1		
	Reference Supp;y Board Assembly (see Figure 5-3)	1702-163220 (881A-403)	89536	1702-163220	1		
	Null Detector Board Assembly (see Figure 5-4)	1702-163212 (881A-402)	89536	1702-163212	1		
	Kelvin-Varley Chassis Assembly (see Figure 5-5)	3158-162495 (881A-404)	89536	3158-162495	1		
	Attenuator Assembly (S/N 123 thru 891) (see Figure 5-6)	3158-166074 (883A-403)	89536	3158-166074	1		
	Attenuator Assembly (S/N 891 and on) (see Figure 5-7)	3158-195461 (887A-402)	89536	3158-195461	1		
	Converter Board Assembly (see Figure 5-8)	1702-166058 (883A-401)	89536	1702-166058	1		
BT1	Battery, nickel-cadmium, 9.6V (883AB)	4002-160408	06860	9.6V/500BH	4		
BT2	Battery, nickel-cadmium, 1.2V (883AB)	4002-160390	06860	1.2 SC	4		
BT3	Battery, nickel-cadmium, 9.6V (883AB)	4002-160408	06860	Same as BT1	REF		
C2	Cap, plstc, 0.47 uf ±20%, 1000V	1507-161612	14752	210B1G474	1		
C3	Cap, cer, 0.1 uf, 500V	1501-105684	56289	41C92	1		Y
CR1, CR2	Diode, Si, 1 amp, 100 PIV (883AB)	4802-116111	14099	SC 1	6	2	
F1	Fuse, 1/16 amp, slow blowing (for 115 volt operation	5101-163030	03614	Type MDL	1	2	
	Fuse, 1/32 amp, slow blowing (for 230 volt operation)	5101-163022	03614	Type MDL	1	2	
	Fuse holder	2102-160846	75915	342004	1		
J4,J5	Binding post, red	2811-142976	58474	DF31RC	4		
P1,J6	Line Cord Assembly	6005-161638	89536	6005-161638	1		
P2	Plug, 3 prong	2109-160275	01730	M-1550-GS	1		
R2,R3	Res, met flm, 4.5M ±1%, 1W	4705-159418	14298	CM-1	2		
R4	Res, met flm, 900K ±1%, 1W	4705-159509	72982	Type MF8C-TO	1		
R5	Res, met flm, 90K ±1%, 1/2W	4705-159426	72982	Type MF7C-TO	1		
R6	Res, met flm, 9K ±1%, 1/2W	4705-159434	72982	Type MF7C-TO	1		
R7	Res, met flm, 1K ±1%, 1/2W	4705-151324	72982	Type MF7C-TO	2		

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R8	Res, var comp, 10K ±20%, 1/2W	4701-162800	12697	Series 37	1		
R9	Res, comp, 62K ±5%, 1/2W (883AB)	4704-108522	04061	EB6235	2		
R10	Res, comp, 10M ±10%, 1/2W	4704-108142	04061	EB1065	1		
R11	Res, comp, 10Ω ±5%, 1W (883AB)	4704-166298	01121	GB1005	1		
R12	Res, comp, 130Ω ±5%, 1W (883AB)	4704-163055	01121	GB1315	2		
S1	SW, power (883A)	5105-162693 (881A-821)	89536	5105-162693	1		
	SW, power (883AB)	5105-163360 (881AB-801)	89536	5105-163360	1		
S2	SW, range	5105-162719 (883A-801)	89536	5105-162719	1		
S3	SW, null	5105-162669 (881A-813)	89536	5105-162669	1		
S4	SW, polarity	5105-200782 (883A-802)	89536	5105-200782	1		
T1	Transformer	5602-162818 (881A-651)	89536	5602-162818	1		
	Cover, large side	3156-162172 (881A-202)	89536	3156-162172	2		
	Cover, small side	3156-162164 (881A-201)	89536	3156-162164	2		
	Cover, top-back	3156-162180 (881A-203)	89536	3156-162180	1		
	Cover, bottom	3156-162198 (881A-204)	89536	3156-162198	1		
	Handle	2404-101857	12136	919-415-173	1		
	Knob, power	3156-162347 (881A-219)	89536	3156-162347	1		
	Knob, polarity and voltage dials	2405-158949 (881A-819)	89536	2405-158949	6		
	Knob, null and range	2405-158956 (881A-820)	89536	2405-158956	2		
	Rubber foot	2819-101253 2819-103309	98388 83478	BH-2097 9102-W	- 4		F G
	Tilt stand	3153-163386 (881A-826)	89536	3153-163386	1		



Figure 5-1. FINAL ASSEMBLY (Sheet 1 of 2)



Figure 5-1. FINAL ASSEMBLY (Sheet 2 of 2)

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	Front Panel Assembly	3158-166066	89536	3158-166066	REF		
		3158-166157	89536	3158-166157	REF		
C1	Cap, plstc, 0.01 uf ±20%, 1000V	1507-159996	84411	663UW103010W	1		
C4*	Cap, elect, 640 uf, -10%, +50%, 6.4V	1502-178608	73445	C437ARC640	1		
J1,J2	Binding post, red	2811-142976	58474	Same as J4	REF		
J3	Binding post, black	2811-142984	58474	DF31BC	1		
M1*	Meter, 100-0-100 ua, 900Ω (883A)	2901-201236	89536	2901-201236	1		
	Meter, 100-0-100 ua, 900Ω (883AB)	2901-201244	89536	2901-201244	1		
R1	Res, comp, 47K ±5%, 1/2W (not shown)	4704-108738	01121	EB4735	0		A
R15*	Res, comp, 270Ω ±10%, 1/2W	4704-108241	01121	EB2711	1		
	Shorting link	2811-101220	24655	938L	1		
	Null Range Shutter	3156-162263	89536	3156-162263	1		
	Nylon Bushing	2502-160499	96881	4L2-FF	9		
	*C2 and R13 provide meter damping. On some instruments, a different meter is used not requiring external damping. The above listing is the preferred replacement.						



Figure 5-2. FRONT PANEL ASSEMBLY

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	Reference Supply Board Assembly without transistors	1702-163220 (881A-403)	89536	1702-163220	REF		
C101	Cap, Al elect, 500 uf -10/+150%, 15V	1502-160101	88419	BR500-15	1	1	
C102	Cap, Al elect, 150 uf -10/+150%, 50V	1502-160119	88419	BR150-50	1	1	
C103	Cap, plstc, 0.022 uf ±10%, 75V	1507-159400	56289	192P2239R75	1		
C104	Cap, plstc, 0.22 uf ±10%, 75V	1507-159392	56289	192P2249R75	2		
C105, C106	Cap, Ta elect, 2.2 uf ±10%, 20V	1508-160226	05397	K2R2C20K	5	2	
C107	Cap, plstc, 0.22 uf ±10%, 75V	1507-159392	56289	Same as C10	REF		
CR101, CR102	Diode, Si, 1 amp, 100 PIV 883A	4802-116111	14099	SC1	4	1	
	883AB	4802-116111	14099	Same as CR1	REF		
Q101	Tstr, Si, NPN (use 4805-117135)	4805-153551	07910	CDQ10449	-		D
	Tstr, Si, NPN (use 4805-193870)	4805-117135	95303	2N2270	1	1	V
	Tstr, Si, NPN	4805-193870	04713	SS2104	8	3	U
Q102 to Q103	Tstr, Si, NPN (use 4805-193870)	4805-153551	07910	CDQ10449	8	3	T
	Tstr, Si, NPN	4805-193870	04713	SS2104	REF		U
Q104	Tstr, Si, PNP (use 4805-190389)	4805-159491	73293	605-9			N
		4805-190389	04713	SM-4144	3	1	O
Q105	Tstr, Ge, PNP	4805-163188	01295	2N404	1	1	
Q106, Q107	Tstr, Ge, NPN	4805-148643	01295	2N1307	2	1	
Q108, Q109	Tstr, Ge, NPN	4805-117127	01295	2N1304	2	1	
R103	Res, var WW, 10K ±10%, 2W	4702-163147	71450	Type 118	1		
R105	Res, comp, 33Ω ±5%, 1W	4704-163063	01121	GB3305	1		
R106	Res, comp, 330Ω ±5%, 1W	4704-163394	01121	GB3315	1		
R107	Res, comp, 1M ±10%, 1/2W	4704-108134	01121	EB1051	3		W
R110	Res, var WW, 500Ω ±10%, 1-1/4W	4702-112433	71450	Type 110	1		
R111	Res, met flm, 23.2K ±1%, 1/2W	4705-159459	75042	Type CEC-TO	2		
R112	Res, met flm, 8.06K ±1%, 1/2W	4705-159467	75042	Type CEC-TO	2		
R113	Res, met flm, 10K ±1%, 1/2W	4705-151274	75042	Type CEC-TO	1		
R114	Res, met flm, 23.2K ±1%, 1/2W	4705-159459	75042	Same as R111	REF		
R117	Res, comp, 10Ω ±10%, 1/2W	4704-108092	01121	EB1001	1		
R119	Res, var WW, 10Ω ±10%, 1-1/4W	4702-112672	71450	Type 110	1		

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R121	Res, var WW, 25Ω ±10%, 1-1/4W	4702-161703	71450	Type 110	1		
R123	Res, var WW, 1K ±20%, 1-1/4W	4702-111575	71450	Type 110	3		
R124	Res, comp, 2.7K ±5%, 1/2W	4704-109074	01121	EB2725	2		
R125	Res, var WW, 1K ±20%, 1-1/4W	4702-111575	71450	Same as R123	REF		
R126	Res, comp, 2.7K ±5%, 1/2W	4704-109074	01121	EB2721	2		
R127, R128	Res, comp, 4.7K ±10%, 1/2W	4704-108381	01121	EB4721	1		
R129, R130	Res, comp, 1K ±10%, 1/2W	4704-108563	01121	EB1021	6		
R131	Res, comp, 82Ω ±5%, 1/2W	4704-108746	01121	EB8205	1		
R132	Res, comp, 8.2K ±5%, 1/2W	4704-147777	01121	EB8225	1		X
	Matched Zener-Res Set	3158-162792 (881A-413)	89536	3158-162792	1	1	
CR103, CR104	Diode, Zener	2			2		
R108	Res, WW, 8K, 1W	1			1		
R109	Res, WW, 16.5K to 20.4K, 1W	1			1		
R115	Res, WW, 25 to 180Ω, 1/8W	1			-		N
	Res, WW, selected, 1/2W	1			1		O
R116	Res, WW, 650Ω ±0.1%, 1/2W	1			-		N
R118	Res, WW, 6K to 10K, 1W	1			1		
	Matched Input Divider Res Set	4710-159848 (881A-414)	89536	4710-159848	1	1	
R100 to R102	Res, WW, 3.3M, 1W	1			3		
R104	Res, WW, 100.05K, 1/4W	1			1		
	Matched Range Divider Res Set	3158-192195 (881A-417)	89536	3158-192195			
R120	Res, WW, 49.488K, 1W	1			1		
R122	Res, WW, 6.111K, 1W	1			1		
	Polyethelene grommet, 3/8 x 1/4	2807-171876	89536	2807-171876	7		
	Polyethelene grommet, 1/2 x 3/8	2807-171884	89536	2807-171884	1		

1 These resistors are factory matched for each instrument. When ordering, include all information stamped on resistor.

2 If replacement is required, the entire Zener- Resistor Set must be replaced.



Figure 5-3. REFERENCE SUPPLY BOARD ASSEMBLY

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	Null Detector Board Assembly	1702-163212 (881A-402)	89536	1702-163212	REF		
C201 to C203	Cap, plstc, .22 uf ±10%, 75V, coated with epoxy resin	1507-162768 (881A-238)	89536	1507-162768	3		
C204	Cap, plstc, 0.047 uf ±20%, 100V	1507-106096	84411	663UW47301	1		
C205	Cap, Al elect, 100 uf -10/+75%, 25V	1502-106518	56289	30D107G025DH4	3	1	
C206	Cap, Al elect, 40 uf -10/+75%, 6V	1502-105205	56289	30D406G006BB4	1	1	
C207	Cap, Al elect, 5 uf -10/+75%, 25V	1502-152009	56289	30D505G025BA4	2	1	
C208, C209	Cap, Al elect, 100 uf -10/+75%, 25V	1502-106518	56289	Same as C205	REF		
C210	Cap, cer, 0.01 uf -20/+80%, 500V	1501-105668	56289	29C9B5	3		
C211	Cap, Al elect, 200 uf -10/+75%, 6V	1502-105189	56289	30D207G006DF4	1	1	
C212	Cap, plstc, 0.0047 uf ±20%, 200V	1507-106054	84411	663UW47202	1		
C213	Cap, Al elect, 20 uf -10/+75%, 50V	1502-106229	56289	30D206G050DC4	3	1	
C214	Cap, cer, 0.01 uf -20/+80%, 500V	1501-105668	56289	Same as C210	REF		
C215	Cap, Al elect, 500 uf -10/+75%, 3V	1502-106328	56289	30D507G003DH4	2	1	
C216	Cap, cer, 0.01 uf -20/+80%, 500V	1501-105668	56289	Same as C210	REF		
C217	Cap, Al elect, 5 uf -10/+75%, 25V	1502-152009	56289	Same as C207	REF		
C218	Cap, Al elect, 20 uf -10/+75%, 50V	1502-106229	56289	Same as C213	REF		
C219	Cap, Al elect, 500 uf -10/+75%, 3V	1502-106328	56289	Same as C215	REF		
C220	Cap, Ta elect, 2.2 uf ±10%, 20V	1508-160226	05397	Same as C105	REF		
CR201, CR202	Diode, Si, 150 ma, 6 PIV	4802-113308	07910	CD13161	2	1	
DS201	Lamp, neon glow, type NE2E, 1/10W, coated with epoxy resin	3902-162776 (881A-239)	89536	3902-162776	1	1	
G201	Chopper, electromechanical, SPDT, coated with epoxy resin	5901-162784 (881A-240)	89536	5901-162784	1	1	
Q201	Tstr, field effect, P-channel	4805-159210	17856	U-112	1	1	
Q202 to Q205	Tstr, Si, NPN (use 4805-193870)	4805-153551	07910	Same as Q102	REF		T
	Tstr, Si, NPN	4805-193870	04713	SS2104			U
Q206	Tstr, Ge, PNP	4805-116129	01295	2N1372	1	1	

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R201	Res, comp, 220K ±10%, 2W	4704-110197	01121	HB2241	1		
R202, R203	Res, comp, 220K ±10%, 1/2W	4704-108217	01121	EB2241	2		
R204	Res, comp, 1M ±10%, 1/2W	4704-108134	01121	Same as R107	REF		
R205	Res, comp, 22K ±10%, 1/2W	4704-108209	01121	EB2231	4		
R206	Res, comp, 1K ±10%, 1/2W	4704-108563	01121	Same as R129	REF		
R207	Res, met flm, 8.06K ±1%, 1/2W	4705-159467	75042	Same as R112	REF		
R208	Res, var WW, 5K ±5%, 2W	4702-111609	71450	Type 115	1		
R209	Res, comp, 10K ±10%, 1/2W	4704-108118	01121	EB1031	2		
R210	Res, comp, 1.8K ±10%, 1/2W	4704-108860	01121	EB1821	2		
R211	Res, comp, 47K ±10%, 1/2W	4704-108480	01121	EB4731	3		
R212	Res, comp, 1K ±10%, 1/2W	4704-108563	01121	Same as R107	REF		
R213	Res, comp, 6.8K ±10%, 1/2W	4704-108399	01121	EB6821	1		
R214	Res, comp, 180Ω ±10%, 1/2W	4704-108571	01121	EB1811	1		
R215	Res, comp, 15K ±10%, 1/2W	4704-108530	01121	EB1531	2		
R216	Res, comp, 47K ±10%, 1/2W	4704-108480	01121	Same as R111	REF		
R217	Res, comp, 9.1K ±5%, 1/2W	4704-160028	01121	EB9125	1		
R218	Res, comp, 27K ±10%, 1/2W	4704-108878	01121	EB2731	2		
R219	Res, comp, 1.8K ±10%, 1/2W	4704-108860	01121	Same as R210	REF		
R220	Res, comp, 39Ω ±10%, 1/2W	4704-160036	01121	EB3901	1		
R221	Res, comp, 7.5K ±5%, 1/2W	4704-108910	01121	EB7525	1		
R222	Res, comp, 22K ±10%, 1/2W	4704-108209	01121	Same as R205	REF		
R223	Res, comp, 10K ±10%, 1/2W	4704-108118	01121	Same as R209	REF		
R224	Res, comp, 1K ±10%, 1/2W	4704-108563	01121	Same as R107	REF		
R225	Res, comp, 3.9K ±10%, 1/2W	4704-161406	01121	EB3921	1		
R226, R227	Res, comp, 47K ±10%, 2W	4704-110015	01121	Same as R211	REF		
R228	Res, comp, 1.5K ±10%, 1/2W	4704-108159	01121	EB1521	1		
R229	Res, met flm, 402Ω ±1%, 1/2W	4705-150839	75042	Type CEC-TO	1		
R230	Res, var WW, 100Ω ±20%, 1-1/4W	4702-112797	71450	Type 110	1		

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R231	Res, var WW, 10K ±5%, 2W	4702-112862	71450	Type 110	1		
R232	Res, met flm, 90.9K ±1%, 1/2W	4705-162974	75042	Type CEC-TO	1		
R233	Res, met flm, 909K ±1%, 1/2W	4705-159483	75042	Type CEC-TO	1		
R234	Res, met flm, 1K ±1%, 1/2W	4705-151324	75042	Same as R7	REF		
R235	Res, met flm, 8.45K ±1%, 1/2W	4705-159475	75042	Type CEC-TO	1		
R236	Res, met flm, 200Ω ±1%, 1/2W	4705-151480	75042	Type CEC-TO	1		
R237	Res, comp, 6.8M ±10%, 1/2W	4704-108662	01121	EB6851	1		
R238	Res, comp, 56K ±10%, 1/2W	4704-108472	01121	EB5631	2		
R239	Res, var comp, 100K ±30%, 3/10W	4701-163402	71450	Type 70	1		
R240	Res, comp, 180K ±10%, 1/2W	4704-108431	01121	EB1841	1		
	Polyethylene grommet, 3/8 x 1/4	2807-171876	89536	2807-171876	6		



Figure 5-4. NULL DETECTOR BOARD ASSEMBLY (Sheet 1 of 2)



Figure 5-4. NULL DETECTOR BOARD ASSEMBLY (Sheet 2 of 2)

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	Kelvin-Varley Assembly	3158-162495 (881A-404)	89536	3158-162495	REF		
C301	Cap, plstc, 1 uf ±20%, 200V	1507-106450	84411	663UW10502	1		
R13	Res, var WW, 2.5K ±1%, 0.75% linear	4711-163121 (881A-407)	89536	4711-163121	1		
R302	Res, met flm, 9.53K ±1%, 1/2W	4705-159442	75042	Type CEC-TO	1		
R303	Res, var WW, 1K ±20%, 1-1/4W	4702-111575	71450	Same as R123	REF		
R304 to R314	Res, WW, 1K, 1/2W	1	89536		33		
R315	Res, WW, 2,499Ω, 1/2W	1	89536		2		
R316	Res, var WW, 2Ω ±10%, 2W	4702-153445	71450	Type 115	9		
R317 to R327	Res, WW, 1K, 1/2W	1	89536	Same as R304	REF		
R328	Res, WW, 2,499Ω, 1/2W	1	89536	Same as R315	REF		
R329	Res, var WW, 2Ω ±10%, 2W	4702-153445	71450	Same as R316	REF		
R330 to R340	Res, WW, 1K, 1/2W	1	89536	Same as R304	REF		
Odd no. from R341 to R363	Res, WW, 4,999.2Ω ±0.01%, 1W	1	89536		12		
Even no. from R342 to R354	Res, var WW, 2Ω ±10%, 2W	4702-153445	71450	Same as R316	REF		
Even no. from R356 to R364	Res, var WW, 2Ω ±10%, 2W (use 4702-182410)	4702-153445	89536	Same as R316	-		H
	Res, var WW, 2Ω ±10%, 2W	4702-182410	89536	4702-182410	5		I
S5	Sw, voltage dial A	5105-162644 (881A-809)	89536	5105-162644	1		
S6	Sw, voltage dial B	5105-162636 (881A-810)	89536	5105-162636	2		
S7	Sw, voltage dial C	5105-162651 (881A-811)	89536	5105-162651	1		
S8	Sw, voltage dial D	5105-162636 (881A-810)	89536	Same as S6	REF		
	Polyethelene grommet 3/8 x 1/4	2807-171876	89536	2807-171876	4		

1 These resistors are factory matched for each instrument. When ordering, include all information stamped on resistor.



Figure 5-5. KELVIN-VARLEY ASSEMBLY

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	NOTE: This assembly used in Models 883A and 883AB, serial numbers 123 thru 891 only.						
	Attenuator Assembly	3158-166074	89536	3158-166074			
	Resistor Set (use 4705-159814)	4705-166884	89536	4705-166884	-		B
	Resistor Set	4705-159814	89536	4705-159814	1		C
R401	Res, met flm, 900K	1			1		
R402	Res, met flm, 109K	1			1		
	Resistor Set (use 4705-159330)	4705-166892	89536	4705-166892	-		B
	Resistor Set	4705-159830	89536	4705-159830	1		C
R404	Res, met flm, 990K	1			1		
R405	Res, met flm, 9.88K	1			1		
	Resistor Set (use 4705-159806)	4705-166900	89536	4705-166900	-		B
	Resistor Set	4705-159806	89536	4705-159806	1		C
R407, R408	Res, met flm, 500K	1			1		
R409	Res, met flm, 976Ω	1			1		
C401	Cap, var glass, 1.0 to 8.5 pf, 1000V specially treated (use 1509-188698)	1509-166868	89536	1509-166868	-		P
	Cap, var alumina, 1.0 to 10 pf, 400V	1509-188698	91293	JMC2903	4		Q
C402	Cap, cer, 33 pf ±10%, 100V	1501-159954	95275	VY10CA330KA	1		
C403	Cap, var glass, 1.0 to 8.5 pf, 1000V specially treated (use 1509-188698)	1509-166868	89536	Same as C401	-		P
	Cap, var alumina, 1.0 to 10 pf, 400V	1509-188698	91293	Same as C401	REF		Q
C404	Cap, cer, 390 pf ±10%, 100V	1501-159962	95275	VY15CA391KA	1		
C405	Cap, var glass, 1.0 to 8.5 pf, 1000V specially treated (use 1509-188698)	1509-166868	89536	Same as C401	-		P
	Cap, var alumina, 1.0 to 10 pf, 400V	1509-188698	91293	Same as C401	REF		Q
C406	Cap, cer, 5.0 pf ±10%, 500V specially treated (use 1501-187682)	1501-166843	89536	1501-166843	-		P
	Cap, cer, 5.0 pf ±5%, 1100V	1501-187682	00656	Type C1-2	2		Q
C407	Cap, mica, 3000 pf ±5%, 100V	1504-161786	88419	CD19F302J	1		
R403	Res, var WW, 5K ±10%, 1W	4701-159905	80740	55PR5K			

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R406	Res, var met flm, 500Ω ±10%, 1W	4701-159897	80740	55PR500	1		
R410	Res, var met flm, 100Ω ±10%, 1W	4701-159889	80740	55PR100	1		
R411	Res, comp, 33K ±5%, 1/2W	4704-108761	01121	EB3335	1		Q

1 These resistors are factory matched for each instrument. When ordering, include all information stamped on resistor.



Figure 5-6. ATTENUATOR ASSEMBLY (S/N 123 thru 891)

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	NOTE: This assembly used in the Models 883A and 883AB beginning with serial number 892.						
	Attenuator Assembly	3158-195461	89536	3158-195461			
	Resistor Set	4705-159814	89536	4705-159814	1		
R401	Res, met flm, 900K	1	89536		1		
R402	Res, met flm, 109K	1	89536		1		
	Resistor Set	4705-159830	89536	4705-159830	1		
R404	Res, met flm, 990K	1	89536		1		
R405	Res, met flm, 9.88K	1	89536		1		
	Resistor Set	4705-159806	89536	4705-159806	1		
R407, R408	Res, met flm, 500K	1	89536		2		
R409	Res, met flm, 976Ω	1	89536		1		
C401	Cap, var, trimmer, 1 to 10 pf, 400V	1509-188698	74970	JMC2903	3		
C402	Cap, cer, 15 pf ±10%, 500V	1501-159947	00656	Type C1-1	1		
C403	Cap, var, trimmer, 1 to 10 pf, 400V	1509-188698	74970	Same as C401	REF		
C404	Cap, mica, 150 pf ±5%, 500V	1504-148478	88419	CD15F151J	1		
C405	Cap, var, trimmer, 1 to 10 pf, 400V	1509-188698	74970	Same as C401	REF		
C406	Cap, cer, 5.0 pf ±5%, 1100V	1501-187682	00656	Type C1-2	1		
C407	Cap, mica, 3,000 pf ±5%, 500V	1504-161786	88719	CD19F302J	1		
R403	Res, var, met flm, 5K ±20%, 3/4W	4701-159905	80740	Type 78P	1		
R406	Res, var, met flm, 500Ω ±20%, 3/4W	4701-159897	80740	Type 78P	1		
R410	Res, var, met flm, 100Ω ±20%, 3/4W	4701-159889	80740	Type 78P	1		
R411	Res, comp, 82K ±5%, 1/4W	4704-188458	01121	CB8235	1		

1 Factory selected. If replacement is required, replace with new Resistor Set.



Figure 5-7. ATTENUATOR ASSEMBLY

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
	Converter Board Assy	1702-166058 (883A-401)	89536	1702-166058			
C501	Cap, cer, 5.1 pf ±10%, 500V specially treated (use 1501-187682)	1501-166843	89536	1501-166843	-		R
	Cap, cer, 5.0 pf ±5%, 1100V	1501-187682	00656	Same as C406	REF		S
C502	Cap, var glass, 0.8 to 8.5 pf, 1250V specially treated (use 1509-188698)	1509-166850	89536	1509-166850	-		R
	Cap, var alumina, 1.0 to 10 pf, 400V	1509-188698	91293	Same as C401	REF		S
C503	Cap, cer, 15 pf ±10%, 500V specially treated (use 1501-159947)	1501-166876	89536	1501-166876	-		R
	Cap, cer, 15 pf ±10%, 500V	1501-159947	00656	Type C1-1	1		S
C504	Cap, plstc, 5 uf ±20%, 20V	1507-160952	00656	V-146-ZR	1		
C505	Cap, Al elect, 30 uf +75/-10%, 15V	1502-106492	56289	30D306G015CB4	1	1	
C506	Cap, Al elect, 250 uf +75/-10%, 12V	1502-160002	56289	30D275G012DH4	2	1	
C507	Cap, mica, 33 pf ±5%, 500V	1504-160317	88419	CD15E330J	1		
C508	Cap, Ta elect, 68 uf ±20%, 6V	1508-160242	05397	K68P6	1	1	
C509	Cap, mica, 22 pf ±5%, 500V	1504-148551	88419	CD15E220J	1		
C510	Cap, Al elect, 250 uf +75/-10%, 12V	1502-160002	56289	Same as C506	REF		
C511	Cap, Ta elect, 10 uf ±10%, 20V	1508-160259	05397	K10C20K	1	1	
C512	Cap, plstc, 0.001 uf ±10%, 200V	1507-159582	56289	192P10292	1		
C513	Cap, Ta elect, 2.2 uf ±10%, 20V	1508-160226	05397	Same as C105	REF		
C514	Cap, Ta elect, 150 uf ±10%, 6V	1508-160234	05397	K150C6K	1	1	
C516	Cap, plstc, 0.00047 uf ±10%, 200V	1507-159574	56289	192P47192	1		
C517	Cap, Ta elect, 150 uf +20/-15%, 15V	1508-160947	56289	109D157C2015TO	1	1	
C518, C519	Cap, plstc, 2 uf ±20%, 10V	1507-160960	00656	V-146-ZR	1		

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
C520	Cap, Al elect, 50 uf +75/-10%, 50V	1502-105122	56289	30K506G050DH4	1	1	
C521	Cap, Ta elect, 2.2 uf ±10%, 20V	1508-160226	05397	Same as C105	REF		
C522	Cap, Al elect, 30 uf +75/-10%, 15V	1502-106492	56289	30K306G015CB4	1	1	
C523	Cap, Al elect, 20 uf +75/-10%, 50V	1502-106229	56289	Same as C213	REF		
CR501	Diode, Si, 10 ma, 20 PIV	4802-161810	03877	SG5337	1	1	
CR502	Diode, Zener, 6.8V at 20 ma (use 4803-187195)	4803-166199	07910	1N754	-		L
	Diode, Zener, 6.8V at 1 ma	4803-187195	07910	CD36554	2	1	M
CR503, CR504	Diode, Si, 10 ma, 20 PIV	4802-161810	03877	SG5337	1	1	
CR505	Diode, Si, 1 amp, 100 PIV (883A)	4802-116111	14099	Same as CR101	REF	1	
	Diode, Si, 1 amp, 100 PIV (883AB)	4802-116111	14099	Same as CR1	REF		
CR506	Diode, Zener, 6.8V at 20 ma (use 4803-187195)	4803-166199	07910	Same as CR502	-		L
	Diode, Zener, 6.8V at 1 ma	4803-187195	07910	Same as CR502	REF		M
CR507	Diode, Si, 1 amp, 100 PIV (883A)	4802-116111	14099	Same as CR101	REF		
	Diode, Si, 1 amp, 100 PIV (883AB)	4802-116111	14099	Same as CR1	REF		
Q501	Tstr, field effect, N-channel	4805-166223	15818	U-1249	1	1	
Q502 to Q506	Tstr, Si, NPN	4805-159855	07910	CDQ23102	1	1	
Q507	Tstr, Si, PNP (use 4805-190389)	4805-159491	73293	Same as Q104	-		N
	Tstr, Si, PNP	4805-190389	04713	Same as Q104	REF		O
Q508	Tstr, Si, NPN (use 4805-193870)	4805-153551	07910	Same as Q102	REF		T
	Tstr, Si, NPN	4805-193870	04713	SS2104	REF		U
Q509	Tstr, Si, PNP (use 4805-190389)	4805-159491	73293	Same as Q104	-		N
	Tstr, Si, PNP	4805-190389	04713	Same as Q104	REF		O
	Resistor Set, matched and specially treated (use 4705-159822)	4705-166918	89536	4705-166918	-		B
	Res Set, matched	4705-159822	89536	4705-159822	1		C
R501	Res, WW, 1M ±1%, 1W	1			1		
R502	Res, WW, 246K ±1/2%, 1W	1			1		
R503	Res, var met flm, 10K ±10%, 1W	4701-159913	80740	55PR10K	1		

1 These resistors are factory matched for each instrument. When ordering, include all information stamped on resistor.

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R504	Res, WW, 125Ω ±1%, 1/4W	4707-159764	15909	Type R1136	1		
R505	Res, comp, 1K ±10%, 1/2W	4704-108563	01121	Same as R129	REF		C
R506	Res, comp, 1M ±10%, 1/2W	4704-108134	01121	Same as R107	REF		
R507	Res, comp, 22K ±10%, 1/2W	4704-108209	01121	Same as R205	REF		
R508	Res, var WW, 10K ±20%, 1-1/4W	4702-112862	71450	Type 110			
R509	Res, comp, 10K ±5%, 1/2W	4704-109165	01121	EB1035	4		
R510	Res, comp, 56K ±10%, 1/2W	4704-108472	01121	Same as R238	REF		
R511	Res, comp, 16K ±5%, 1/2W	4704-159632	01121	EB1635	1		
R512	Res, comp, 10K ±5%, 1/2W	4704-109165	01121	Same as R509	REF		
R513	Res, comp, 270Ω ±5%, 1/2W	4704-159616	01121	EB2715	1		
R514	Res, comp, 2.7K ±5%, 1/2W	4704-109074	01121	Same as R124	REF		
R515	Res, comp, 8.2Ω ±5%, 1/2W	4704-159590	01121	EB82G5	1		
R516	Res, comp, 68K ±5%, 1/2W	4704-159624	01121	EB6835	1		
R517	Res, comp, 27K ±10%, 1/2W	4704-108878	01121	Same as R218	REF		
R518	Res, comp, 3.3K ±10%, 1/2W	4704-108373	01121	EB3321	1		
R519	Res, comp, 15K ±10%, 1/2W	4704-108530	01121	Same as R215	REF		
R520	Res, comp, 470Ω ±5%, 1/2W	4704-108787	01121	EB4715	1		
R521	Res, comp, 62K ±5%, 1/2W (883A)	4704-108522	01121	EB6235	1		
	Res, comp, 62K ±5%, 1/2W (883AB)	4704-108522	01121	Same as R9	REF		
R522	Res, var comp, 100K ±30%, 1/2W	4701-160010	71450	Type UPE70	1		
R523	Res, comp, 300Ω ±5%, 1/2W	4704-108829	01121	EB3015	1		
R524	Res, comp, 47Ω ±5%, 1/2W	4704-159608	01121	EB4705	1		
R525	Res, comp, 470Ω ±5%, 1/2W	4704-108787	01121	EB4715	1		
R526	Res, comp, 330Ω ±5%, 1/2W	4704-108936	01121	EB3315	2		
R527	Res, comp, 10K ±5%, 1/2W	4704-109165	01121	Same as R509	REF		
R528	Res, comp, 100K ±10%, 1/2W	4704-108126	01121	EB1041	1		
R529	Res, comp, 5.6K ±10%, 1/2W (use 4704-108837)	4704-108324	01121	EB5621	-		J
	Res, comp, 2.7K ±10%, 1/2W	4704-108837	01121	Same as R126	REF		K

REF DESIG.	DESCRIPTION	FLUKE STOCK NO.	MFR.	MFR. PART NO.	TOT. QTY.	REC. QTY.	USE CODE
R530, R531	Res, WW, 547Ω ±0.1%, 1/4W	4707-159772	15909	Type R1136	2	1	
R532, R533	Res, met flm, 51.1K ±1%, 1/2W	4705-159665	75042	Type CEC-TO	1		
R534	Res, comp, 330Ω ±5%, 1/2W	4704-108936	01121	Same as R526	REF		
R535	Res, comp, 2.2K ±5%, 1/2W	4704-108506	01121	EB2225	1		
R536	Res, comp, 1.5M ±10%, 1/2W	4704-108175	01121	EB1551	1		
R537	Res, comp, 22K ±10%, 1/2W	4704-108209	01121	Same as R205	REF		
R538	Res, met flm, 10K ±10%, 1/2W	4705-151274	75042	Type CEC-TO	1		
R539	Res, var WW, 3K ±20%, 2W	4702-153429	71450	Type 115	1		
R540	Res, met flm, 5.11K ±1%, 1/2W	4705-159657	75042	Type CEC-TO	1		
R541	Res, met flm, 1.1Ω ±5%, 1/2W	4704-163717	01121	EB11G5	1		
R542	Res, met flm, 10K ±5%, 1/2W	4704-109165	01121	Same as R509	REF		
R543	Res, met flm, 24K ±5%, 1/2W	4704-108654	01121	EB2435	1		
R544	Res, met flm, 22M ±10%, 1/2W	4704-108233	01121	EB2261	1		
R545	Res, met flm, 130Ω ±5%, 1W (883A)	4704-163055	01121	Same as R12	REF		
	Res, met flm, 130Ω ±5%, 1W (883AB)	4704-163055	01121	Same as R12	REF		



Figure 5-8. CONVERTER BOARD ASSEMBLY (Sheet 1 of 2)



Figure 5-8. CONVERTER BOARD ASSEMBLY (Sheet 2 of 2)

5-11. USE CODE EFFECTIVITY

5-12. The following list of use codes is intended to allow the customer to determine the effectivity of all replaceable parts. All parts with no code are used on all instruments with serial numbers above 123. New codes will be added as necessary on forthcoming instruments.

USE CODE	
No Code	Model 883A & 883AB serial number 123 and on
A	Model 883A & 883AB serial number 123 to 127
B	Model 883A & 883AB serial number 123 to 147
C	Model 883A & 883AB serial number 148 and on
D	Model 883A & 883AB serial number 123 to ~ 150
E	Model 883A & 883AB serial number ~ 151 and on
F	Model 883A & 883AB serial number 123 to ~ 200
G	Model 883A & 883AB serial number ~ 201 and on
H	Model 883A & 883AB serial number 123 to ~ 351
I	Model 883A & 883AB serial number ~ 352 and on
J	Model 883A & 883AB serial number 123 to 375
K	Model 883A & 883AB serial number 376 and on
L	Model 883A & 883AB serial number 123 to 514
M	Model 883A & 883AB serial number 515 and on
N	Model 883A & 883AB serial number 123 to ~ 550
O	Model 883A & 883AB serial number ~ 551 and on
P	Model 883A & 883AB serial number 123 to 569
Q	Model 883A & 883AB serial number 570 and on
R	Model 883A & 883AB serial number 123 to 589
S	Model 883A & 883AB serial number 590 and on
T	Model 883A & 883AB serial number 123 to 750
U	Model 883A & 883AB serial number 751 and on
V	Model 883A & 883AB serial number ~ 151 to 750
W	Model 883A & 883AB serial number 123 to 920
X	Model 883A & 883AB serial number 921 and on
Y	Model 883A & 883AB serial number 751 to 931

SECTION VI

ACCESSORIES

6-1. PRECISION VOLTAGE DIVIDERS

6-2. The FLUKE 80A, 80D, and 80E Voltage Dividers provide the FLUKE 800 Series Differential Voltmeters with the ability to make high accuracy measurements up to 30,000 volts DC. All models contain a zero center panel meter which allows the polarity and approximate magnitude of the unknown high voltage to be easily observed. At maximum input, all units draw but 1 ma of current from the unknown. The extreme accuracy and excellent long term stability of these dividers are obtained by using properly aged precision wirewound resistors which have a very low temperature coefficient. To further ensure high accuracy and long term stability at very high voltages, the 80D dividers have all resistance components immersed in oil within a hermetically sealed container. As an additional feature, all 80D and 80E models are provided with a 1 volt tap which allows measurements of high voltages with a laboratory potentiometer. Specifications for the standard models are shown on next page. Other intermediate models are available upon special request.



MODEL 80A

MODEL 80D



MODEL 80E

Model No.	Maximum Input Voltage	Total Resistance	Current Drawn At Max. Input	Division Ratio			Division Ratio Accuracy	Stability of Division Accuracy Per Year
				500V Out	10V Out	1V Out		
80A-1	1 KV	1 M	1 ma	2:1	——	——	±0.015%	——
80A-2	2 KV	2 M	1 ma	4:1	——	——	±0.015%	——
80E-5	5 KV	5 M	1 ma	—	500:1	5,000:1	±0.01%	±0.01%
80E-10	10 KV	10 M	1 ma	—	1000:1	10,000:1	±0.01%	±0.01%
80D-30	30 KV	30 M	1 ma	60:1	3000:1	30,000:1	±0.01%	±0.01%

MODELS	SIZE	INPUT CONNECTOR	OUTPUT CONNECTOR
80A	6-3/4" high 5-1/4" wide 2-1/4" deep	UG-560U with mating connector supplied	Insulated binding posts on 3/4" centers
80E	7" high 8-1/2" wide 8" deep	MS3102A-18-165 with mating connector supplied	Insulated binding posts on 3/4" centers for both outputs
80D	13" high 9-3/4" wide 16" deep	Special 5" ceramic standoff with mating 6" guard supplied	Insulated binding post on 3/4" centers for both outputs



MODEL A88 ISOLATION AMPLIFIER

6-3. ISOLATION AMPLIFIER

6-4. The FLUKE Model A88 all solid-state isolation amplifier is designed to provide isolation between the output of a differential voltmeter and the input of a recorder. Thus, the A88 will allow the use of a wide range of strip chart recorders for recording the voltmeter reading without regard to the input isolation characteristics of the recorder. The A88 is also excellent for making accurate dc microvolt and nanoampere measurements in the presents of common mode voltages up to 1100 vdc and 3 vac, 50 to 500 cycles.

GAIN: 1 volt output per microampere input.

GAIN ACCURACY: ±2%.

INPUT CURRENT RANGE: 0 to 2 microamperes.

INPUT VOLTAGE RANGE: 0 to 2 millivolts nominal.

INPUT RESISTANCE: 950 ohms (±5%).

OUTPUT VOLTAGE RANGE: 0 to 2 volts open circuit.

OUTPUT RESISTANCE: 1000 ohms (±5%).

INPUT ISOLATION FROM CHASSES: Greater than 5×10^{11} ohms at 25°C (77°F), 60% RH and 1×10^{10} ohms at 50°C (122°F), 80% RH.

APPENDIX A

FEDERAL SUPPLY CODE FOR MANUFACTURERS

A-1. CODE TO NAME

A-2. The following five-digit code numbers are listed in numerical sequence along with the manufacturer's name and address to which the code has been assigned. The Federal Supply Code has been taken from Cataloging Handbook H 4-2, Code to Name. Suppliers not listed in the Federal Supply Code for Manufacturers have been assigned an alphabetical code by FLUKE.

00213	Sage Electronics Corp. Rochester, New York
00327	Welwyn International, Inc. Cleveland, Ohio
00656	Aerovox Corp. New Bedford, Massachusetts
01121	Allen-Bradley Company Milwaukee, Wisconsin
01281	Pacific Semiconductors Inc. Lawndale, California
01295	Texas Instruments, Inc. Semiconductor Components Div. Houston, Texas
01730	Circle Mfg. Co. Inc. Little Falls, New Jersey
01884	Dearborn Electronic Labs Inc. Orlando, Florida
01963	Cherry Electrical Products Corp. Highland Park, Illinois
02660	Amphenol-Borg Elect. Corp. Chicago, Illinois
02606	Fenwal Laboratories Inc. Framington, Massachusetts
02799	Arco Capacitors, Inc. Los Angeles, California
03614	Bussmann Mfg. Div. of McGraw-Edison Co. Los Angeles, California
03615	Ohmite Mfg. Co. Los Angeles, California
03877	Transitron Electronic Corp. Wakefield, Massachusetts
03911	Clairex Corp. New York, New York
03980	Muirhead Instruments, Inc. Mountainside, New Jersey
04009	Arrow Hart and Hegemen Electronic Company Hartford, Connecticut
04062	Elmenco Products Company New York, New York
04202	Winchester Electronics Co. New Milford, Connecticut
04221	Telex-Aemco Division of Telex Corp. Mankato, Minnesota
04645	Kurz-Kasch, Inc. Chicago, Illinois
04713	Motorola Inc. Semiconductor Products Division Phoenix, Arizona
05082	Tung-Sol Electric Inc. Melrose Park, Illinois
05278	Penn-East Engrg. Corp. Kutztown, Pennsylvania
05397	Union Carbide Corp. Linde Division Kemet Dept. Cleveland, Ohio
05571	Sprague Electric Company Culver City, California
05704	Alac, Inc. Glendale, California
06001	General Electric Company Capacitor Department Irmo, South Carolina
06136	Ward Leonard Electric Co. Los Angeles, California
06473	Amphenol Space and Missile Sys Chatsworth, California
06555	Beede Electrical Inst. Co. Penacook, New Hampshire
06751	Nuclear Corporation of America, Inc. U. S. Semcor Div. Phoenix, Arizona
06860	Gould National Batteries Inc. La Puente, California
07115	Corning Glass Works Electronic Components Dept. Bradford, Pennsylvania
07263	Fairchild Semiconductor Div. of Fairchild Camera and Instrument Corp. Mountain View, California
07344	Bircher Co., Inc. Rochester, New York
07792	Lerma Engineering Corp. Northampton, Massachusetts
07910	Continental Device Corp. Hawthorne, California
08530	Reliance Mica Corp. Brooklyn, New York
08863	Nylomatic Corp. Morrisville, Pennsylvania
08988	Skottie Electronics Inc. Peckville, Pennsylvania
11237	Chicago Telephone of Calif Inc. South Pasadena, California
11503	Keystone Mfg. Co. Warren, Michigan
12060	Diodes, Inc. Chatsworth, California
12136	Philadelphia Handle Co. Camden, New Jersey
12400	International Resistance Co. Control Components Division Philadelphia, Pennsylvania
12617	Hamlin Inc. Lake Mills, Wisconsin
12697	Clarostat Mfg. Co. Dover, New Hampshire
14099	Semtech Corp. Newbury Park, California
14193	California Resistor Corp. Santa Monica, California
14298	American Components Inc. Conshohocken, Pennsylvania
14752	Electro Cude Inc. South Pasadena, California
15818	Amelco Inc. Mountain View, California
15909	Daven Division Thomas A. Edison Ind. McGraw Edison Co. Livingston, New Jersey
16332	Milwaukee Relays Inc. Cedarburg, Wisconsin
16473	Cambridge Scientific Industries Inc. Cambridge, Maryland
17069	Circuit Structures Lab Santa Ana, California
17856	Siliconix Inc. Sunnyvale, California
17910	Continental Device Corp. Hawthorne, California
18083	Clevite Corp. Transistor Division Palo Alto, California
19429	Montronics, Inc. Seattle, Washington
19701	Electra Mfg. Co. Independence, Kansas
24655	General Radio Co. West Concord, Mass.
28520	Heyman Mfg. Co. Kenilworth, New Jersey
33173	General Electric Co. Tube Dept. Owensboro, Kentucky
37942	P. R. Mallory and Co., Inc. Indianapolis, Indiana
38315	Honeywell Inc. Precision Meter Division Manchester, New Hampshire
42498	National Company, Inc. Malden, Massachusetts
44655	Ohmite Mfg. Co. Skokie, Illinois
49671	Radio Corp. of America New York, New York
53021	Sangamo Electric Co. Springfield, Illinois
55026	Simpson Electric Company Chicago, Illinois
56289	Sprague Electric Co. North Adams, Mass.
58474	Superior Electric Co. Bristol, Connecticut
60399	Torrington Mfg. Co. Torrington, Connecticut
62460	USHCO Mfg. Co., Inc. Buffalo, New York
64834	West Mfg. Co. San Francisco, California
65092	Weston Instruments Div. of Daystrom, Inc. Newark, New Jersey
66150	Winslow Tele-Tronics Inc. Asbury Park, New Jersey
70563	Amperite Co. Union City, New Jersey
70903	Belden Mfg. Co. Chicago, Illinois

71400 Bussman Manufacturing Division of McGraw Edison Co. St. Louis, Missouri

71450 CTS Corp. Elkhart, Indiana

71468 Cannon Electric Company Los Angeles, California

71482 Clare, C. P. and Company Chicago, Illinois

71590 Centralab Div. of Globe Union, Inc. Milwaukee, Wisconsin

71707 Coto Coil Co., Inc. Providence, Rhode Island

71744 Chicago Miniature Lamp Works Chicago, Illinois

71785 Cinch Mfg. Co. and Howard B. Jones Div. Chicago, Illinois

72005 Driver, Wilber B., Co. Newark, New Jersey

72092 Eitel-McCullough, Inc. San Bruno, California

72136 Electro Motive Mfg. Co. Willimantic, Connecticut

72354 Fast, John E. Co. Div. of Victoreen Instr. Co. Chicago, Illinois

72559 Essex Electronics Inc. Berkeley Heights, New Jersey

72619 Dialight Corp. Brooklyn, New York

72665 Mallory Battery Company Cleveland, Ohio

72982 Erie Tech. Products Inc. Erie, Pennsylvania

73138 Helipot Division of Beckman Instruments Inc. Fullerton, California

73293 Hughes Products Div. of Hughes Aircraft Co. Newport Beach, California

73445 Amperex Electronic Co. Div. of North American Philips Co., Inc. Hicksville, New York

73559 Carling Electric Inc. Hartford, Connecticut

73586 Circle F Mfg. Co. Trenton, New Jersey

73899 JFD Electronics Corp. Brooklyn, New York

73949 Guardian Electric Mfg. Co. Chicago, Illinois

74217 Radio Switch Corp. Marlboro, New Jersey

74306 Piezo Crystal Company Carlisle, Pennsylvania

74542 Hoyt Elect. Instr. Works Penacook, New Hampshire

74970 Johnson, E. F., Co. Waseca, Minnesota

75042 International Resistance Co. Philadelphia, Pennsylvania

75915 Littelfuse Inc. Des Plaines, Illinois

76854 Oak Mfg. Co. Crystal Lake, Illinois

77342 American Machine and Foundry Company Potter & Brumfield Div. Princeton, Indiana

77969 Rubbercraft Corp. of California Ltd. Torrance, California

78277 Sigma Instruments, Inc. South Braintree, Mass.

79136 Waldes Kohinoor Inc. Long Island City, New York

79497 Western Rubber Company Goshen, Indiana

80031 Mepco Division of Sessions Clock Co. Morristown, New Jersey

80294 Bourns Laboratories, Inc. Riverside, California

80583 Hammarlund Company, Inc. New York, New York

80640 Stevens, Arnold Co., Inc. Boston, Massachusetts

81073 Grayhill Company La Grange, Illinois

81439 Therm-O-Disc Inc. Mansfield, Ohio

81483 International Rectifier Corp El Segundo, California

81590 Korry Mfg. Co. Seattle, Washington

82376 Astron Division Renwell Industries Inc. East Newark, New Jersey

82389 Switchcraft Inc. Chicago, Illinois

82872 Roanwell Corp. Brooklyn, New York

82877 Rotron Mfg. Co., Inc. Woodstock, New York

82879 Royal Electric Corp. Pawtucket, Rhode Island

83003 Varo Mfg. Co., Inc. Garland, Texas

83298 Bendix Corp. Red Bank Division Red Bank, Eatontown, New Jersey

83330 Smith, Herman H., Inc. Brooklyn, New York

83478 Rubbercraft Corp. of Am. New Haven, Connecticut

84411 Good All Electric Mfg. Co. Ogallala, Nebraska

86689 R. M. B. Corp. Los Angeles, California

88419 Cornell-Dubilier Elec. Corp. Electro-Mechanical Div. Fuquay Springs, North Carolina

88690 Essex Wire Corp. R. B. M. Division Detroit, Michigan

89536 Fluke, John, Mfg. Co., Inc. Seattle, Washington

89730 General Electric Company Newark Lamp Works of Lamp Division of Consumer Products Group GECO Newark, New Jersey

90205 Best Stamp and Mfg. Co. Kansas City, Missouri

90211 Square D Company Chicago, Illinois

90303 Mallory Battery Company North Tarrytown, New York

91293 Johanson Mfg. Co. Boonton, New Jersey

91407 Superior Electric Company Oak Park, Illinois

91662 Elco Corp. Willow Grove, Penn.

91737 Gremar Mfg. Co., Inc. Wakefield, Massachusetts

91802 Industrial Devices, Inc. Edgewater, New Jersey

91929 Minneapolis Honeywell Regulator Company Micro Switch Division Freeport, Illinois

91934 Miller Electric Co., Inc. Pawtucket, Rhode Island

93332 Sylvania Electric Products Inc. Semiconductor Products Division Woburn, Massachusetts

94145 Raytheon Company Semiconductor Division California Street Plant Newton, Massachusetts

95146 Alco Electronics Mfg. Co. Lawrence, Massachusetts

95264 Lerco Electronics Inc. Burbank, California

95303 Radio Corp. of America Comm. Receiving Tube & Semiconductor Division Cincinnati, Ohio

95354 Methode Mfg. Co. Chicago, Illinois

95712 Dage Electric Co., Inc. Franklin, Indiana

96733 San Fernando Electric Mfg. Co. San Fernando, California

96881 Thomson Industries, Inc. New Hyde Park Long Island, New York

97945 S. S. White Dental Mfg. Co. Plastics Division New York, New York

97966 CBS Electronics Div. of Columbia Broadcasting System, Inc. Danvers, Massachusetts

98094 Penta Laboratories, Inc. Santa Barbara, California

98388 Accurate Sales Company Culver City, California

98743 James Vibrapower Corp. Chicago, Illinois

98925 Semiconductor Division of Clevite Corp. Waltham, Massachusetts

99120 Plastic Capacitors, Inc. Chicago, Illinois

99217 Southern Electronics Corp. Burbank, California

99515 Marshall Industries Electron Prod. Div. Pasadena, California

Revised May 15, 1966
Using H4-2 Dated March 1963

WARRANTY

The JOHN FLUKE MFG. CO., INC. warrants each instrument manufactured by them to be free from defects in material and workmanship. Their obligation under this Warranty is limited to servicing or adjusting an instrument returned to the factory for that purpose, and to making good at the factory any part or parts thereof; except tubes, fuses, choppers and batteries, which shall, within one year after making delivery to the original purchaser, be returned by the original purchaser with transportation charges prepaid, and which upon their examination shall disclose to their satisfaction to have been thus defective. If the fault has been caused by misuse or abnormal conditions of operation, repairs will be billed at a nominal cost. In this case, an estimate will be submitted before work is started, if requested.

If any fault develops, the following steps should be taken.

1. Notify the John Fluke Mfg. Co., Inc., giving full details of the difficulty, and include the Model number, type number, and serial number. On receipt of this information, service data or shipping instructions will be forwarded to you.

2. On receipt of the shipping instructions, forward the instrument prepaid, and repairs will be made at the factory. If requested, an estimate of the charges will be made before the work begins, provided the instrument is not covered by the Warranty.

SHIPPING

All shipments of John Fluke Mfg. Co., Inc. instruments should be made via Railway Express prepaid. The instrument should be shipped in the original packing carton; or if it is not available, use any suitable container that is rigid. If a substitute container is used, the instrument should be wrapped in paper and surrounded with at least four inches of excelsior or similar shock-absorbing material.

CLAIM FOR DAMAGE IN SHIPMENT

The instrument should be thoroughly inspected immediately upon receipt. All material in the container should be checked against the enclosed packing list. The manufacturer will not be responsible for shortages against the packing sheet unless notified immediately. If the instrument fails to operate properly, or is damaged in any way, a claim should be filed with the carrier. A full report of the damage should be obtained by the claim agent, and this report should be forwarded to John Fluke Mfg. Co., Inc. Upon receipt of this report you will be advised of the disposition of the equipment for repair or replacement. Include the model number, type number, and serial number when referring to this instrument for any reason.

The John Fluke Mfg. Co., Inc. will be happy to answer all application questions which will enhance your use of this instrument. Please address your requests to:

JOHN FLUKE MFG. CO., INC., P. O. BOX 7428, SEATTLE 33, WASHINGTON

Sales and Service Representatives

ALABAMA

HUNTSVILLE
BCS Associates, Inc.
2317 Bob Wallace Ave. S.W.
Tel. (205) 534-1648

ALASKA

SEATTLE
Instrument Specialists, Inc.
5950 Sixth Ave. South
Suite 106
Seattle, Washington
Tel. (206) 767-4260

ARIZONA

PHOENIX
Barnhill Associates
4900 E. Indian School Road
Tel. (602) 959-2115

CALIFORNIA

LOS ANGELES
Instrument Specialists, Inc.
2870 Los Feliz Place
Tel. (213) 665-5181

SAN FRANCISCO
Instrument Specialists, Inc.
2359 De La Cruz
Santa Clara, California
Tel. (408) 244-1505

COLORADO

DENVER
Barnhill Associates
1170 S. Sheridan Blvd.
Tel (303) 934-5505

CONNECTICUT

HARTFORD
Instrument Representatives, Inc.
P.O. Box 165
Glastonbury, Connecticut
Tel. (203) 633-0777

FLORIDA

ORLANDO
BCS Associates, Inc.
940 N. Fern Creek Ave.
Tel. (305) 425-2764

HAWAII

HONOLULU
Industrial Electronics, Inc.
646 Queen Street
Tel. (808) 506-095

ILLINOIS

CHICAGO
Cozzens & Cudahy, Inc.
9501 W. Devon Ave.
Rosemont, Illinois
Tel. (312) 825-1144

INDIANA

INDIANAPOLIS
Cozzens & Cudahy, Inc.
44 Kirk Drive
Tel. (317) 244-2456

LOUISIANA

NEW ORLEANS
BCS Associates, Inc.
P.O. Box 7371
Metairie, Louisiana
Tel. (504) 888-2266

MARYLAND

BALTIMORE
Electronic Marketing Assoc.
11501 Huff Court
Kensington, Maryland
Tel. (301) 744-7700

MASSACHUSETTS

BOSTON
Instrument Representatives, Inc.
1046 Massachusetts Avenue
Arlington, Massachusetts
Tel. (617) 646-1034

MICHIGAN

DETROIT
Technitron, Inc.
13657 Grand River Ave.
Tel. (313) 838-7324

MINNESOTA

MINNEAPOLIS
Cozzens & Cudahy, Inc.
7710 Computer Ave.
Tel. (612) 920-1022

MISSOURI

ST. LOUIS
Cozzens & Cudahy, Inc.
10534 Natural Bridge Road
Edmundson, Missouri
Tel. (314) 423-1234

NEW JERSEY

NEWARK
SBM Associates, Inc.
1519 Stuyvesant Avenue
Union, New Jersey
Tel. (201) 687-8737

NEW MEXICO

ALBUQUERQUE
Barnhill Associates
827 Pennsylvania Ave.
Tel. (505) 265-7766

NEW YORK

NEW YORK
SBM Associates, Inc.
28 Hobby Street
Pleasantville, New York
Tel. (914) 769-1811

LONG ISLAND
SBM Associates, Inc.
528 Old Country Road
Plainview, Long Island
Tel. (516) 433-1421

ROCHESTER
SBM Associates, Inc.
800 Linden Avenue
Tel. (716) 381-8330

SYRACUSE
SBM Associates, Inc.
138 Pickard Bldg.
5858 E. Molloy Road
Tel. (315) 454-9377

NORTH CAROLINA

GREENSBORO
BCS Associates, Inc.
1039 E. Wendover Avenue
Tel. (919) 273-1918

OHIO

CLEVELAND
Technitron, Inc.
23203 Lorain Road
North Olmsted, Ohio
Tel. (216) 734-0960

DAYTON
Technitron, Inc.
1250 W. Dorothy Lane
Tel. (513) 298-9964

OREGON

PORTLAND
Instrument Specialists, Inc.
5950 Sixth Ave. South
Suite 106
Seattle, Washington
Tel. (206) 767-4260

PENNSYLVANIA

PHILADELPHIA
Acromatix Associates, Inc.
3118 Germantown Pike
Fairview Village, Pennsylvania
Tel. (215) 279-0377

PITTSBURGH
Technitron, Inc.
114 Spring Grove Road
Tel. (412) 371-1231

TEXAS

DALLAS
Barnhill Associates
507B Bishop Street
Richardson, Texas
Tel. (214) AD 1-2573

HOUSTON
Barnhill Associates
Suite 203
3810 Westheimer
Tel. (713) NA 1-0040

WASHINGTON

SEATTLE
Instrument Specialists, Inc.
5950 Sixth Ave. South
Suite 106
Seattle, Washington
Tel. (206) 767-4260

WASHINGTON, D.C.

Electronic Marketing Associates
11501 Huff Court
Kensington, Maryland
Tel. (301) 946-0300

CANADA

BRITISH COLUMBIA

VANCOUVER
Allan Crawford Associates, Ltd.
5901 East Broadway
North Burnaby 2, B.C.
Tel. (604) 291-7161

ONTARIO

OTTAWA
Allan Crawford Associates, Ltd.
376 Churchill Avenue — Suite 106
Tel. (613) 725-1288

TORONTO
Allan Crawford Associates, Ltd.
65 Martin Ross Avenue
Downsview, Ontario
Tel. (416) 636-4910

QUEBEC

MONTREAL
Allan Crawford Associates, Ltd.
6999 Cote de Neiges Road
Tel. (514) 739-6776

International Representatives

AUSTRALIA

Elmesco Instruments
41 Carter Road
Brookvale, N.S.W., Australia

AUSTRIA

Omni Ray AG
Techn. Beratung
Mollardgasse 54
Vienna VI, Austria

BELGIUM

C. N. Rood S/A
30 Rue Leon Frederic
Brussels 4, Belgium

DENMARK

Tage Olsen A/S
Ronnegade 1-0
Copenhagen, Denmark

FINLAND

Oy Findip AB Ltd.
Mannerheimintie 29C
Helsinki 25, Finland

FRANCE

S. E. R. I. E. L., s. a.
48 Avenue Victor Hugo
Clamart (Seine) France

HONG KONG and MACAO

Intronics Ltd.
4 Hankow Road, Suite 4A
Kowloon, Hong Kong

ISRAEL

R. D. T. Electronics
Engineering Ltd.
P.O. Box 21082
13 Dov-Hos Street
Tel-Aviv, Israel

ITALY

Elettronucleonica s. p. a.
7 Pizza DeAngli
20146 Milano, Italy

JAPAN

Toyo Trading Co., Ltd.
Central P.O. Box 999
Tokyo, Japan

Toyo Trading Co., Ltd.
4-37, Minamihonmachi
Higashika, Osaka, Japan

KOREA

M. - C International
Room 516, Bando Building
Seoul, Korea

THE NETHERLANDS

C. N. Rood N. V.
Post Office Box 4542
Rijswijk (Z. H.) The Netherlands

Fluke Nederland N. V.
Post Office Box 5053
Tilburg, The Netherlands

NEW ZEALAND

Sample Electronics (N. Z.) Ltd.
8 Matipo Street
Onehunga
Auckland, New Zealand

NORWAY

Morgenstierne & Co. A/S
Wesselsgt. 6
Oslo, Norway

OKINAWA

RYUKYU ISLANDS

Baxter Trading Co.
P.O. Box 26
Koza, Okinawa
Ryukyu Islands

PHILIPPINES

T. J. Wolff
2246 Pasong Tamo
Makati, Rizal
Manila, Philippines

SOUTH AFRICA

A. C. Gowlett (Pty.) Ltd.
P.O. Box 1257
Johannesburg, So. Africa

A. C. Gowlett (Pty.) Ltd.
P.O. Box 3641
Cape Town, So. Africa

A. C. Gowlett (Pty.) Ltd.
P.O. Box 2143
Durban, Natal, So. Africa

SOUTH VIETNAM

R. B. Landis & Co., Inc.
216 Hien-Vuong
P.O. Box H-3
Saigon, Vietnam

SPAIN

REMA
Calle General Sanjurjo, 18
Madrid, Spain

SWEDEN

Robert E. O. Olsson
Box 165
Tradgardsgatan 7
Motala, Sweden

SWITZERLAND

Omni Ray AG
Dufourstrasse 56
8008 Zurich, Switzerland

TAIWAN

Heighten Scientific Co., Ltd.
P.O. 1408
Taipei, Taiwan

THAILAND

G. Simon Radio Ltd.
30 Patpong Avenue
Suriwong
Bangkok, Thailand

THE UNITED KINGDOM

Fluke International Corp.
P.O. Box 102
Watford-Herts, England

WEST GERMANY

Rohde & Schwarz Vertriebs - Gmbh
5000 Koeln
Hohe Strasse 160-168
West Germany

Rohde & Schwarz Handels - Gmbh
1000 Berlin 10
Ernst - Reuter - Platz 10
West Germany

Rohde & Schwarz Vertriebs - Gmbh
2000 Hamburg 50
Grosse Bergstrasse 213-217
West Germany

Rohde & Schwarz Vertriebs - Gmbh
7500 Karlsruhe
Kriegsstrasse 39
West Germany

Rohde & Schwarz Vertriebs - Gmbh
8000 Muenchen
Dachauer Strasse 109
West Germany

In Europe contact FLUKE NEDERLAND, N. V., Post Office Box 5053, Tilburg, The Netherlands

FLUKE


CHANGES
1. For 883A & 883AB ser 123 to 127
R1 (47K) was in series with C1
2. For 883A & 883AB ser 123 to 147
R505 was not used
3. For 883A & 883AB ser 123 to 375
R529 was 5.6K
4. For 883A & 883AB ser 123 to 550
R115 (selected) was in series
with R116 (600Ω)
5. For 883A & 883AB ser 123 to 565
C401, C403, & C405 were 1.0 to
8.5 pf R411 was not used
6. For 883A & 883AB ser 123 to 589
C501 was 3.1 pf
C502 was 1.0 to 8.5 pf
7. ⑦ was used in the 883A and 883AB
prior ser 731 to 921, inclusive
8. R107 removed at S/N 920
R132 added at S/N 921
9. At S/N 892:
C602 was changed from 33 pf to 15 pf
C604 was changed from 390 pf to 150 pf
R411 was changed from 33K to 82K
VOLTAGE RANGE
NULL RANGE
LO
MED LO
MED HI
HI
.1
.01
.001
.0001
1
.1
.01
.001
10
1
.1
.01
100
10
1
.1
1000
100
10
1
NOTES:
REFERENCE DESIGNATIONS
BT1-3
C1-4, 101-107, 201, 301, 401-407, 501-514, 516-523
CR1-3, 101-104, 201-202, 501-507
DS 201
G201
J1-6
M1
P1-2
Q101-109, 201-206, 501-509
R1-15, 100-115, 117-132, 201-240, 302-364, 401-411, 501-545
S1-8
T1
F1
ALL FLAGNOTES WITH THE SAME NUMBER ARE CONNECTED.
INDICATES -18V RETURN
INDICATES -5V AND -15V RETURN
DETAIL I
DETAIL II
DETAIL III
PANEL READOUT
FUNCTIONAL SCHEMATIC
DIFFERENTIAL VOLTMETER
MODELS 883A and 883AB
883A SER. NO. 123 & ON
883AB SER. NO. 133 & ON
FLUKE
JOHN FLUKE MFG. CO. INC.
P.O. Box 7428 Seattle, Washington 98133

www.manualsplus.com
1020884